

MEMO. FOR. M^r RITCHIE, WOKINGHAM.

S.S. "SINGKEP"

The particulars of the boilers shown on 1st Entry Report (San Francisco Oct. No. 8608A) do not warrant the assignment of a working pressure of 213 $\text{lb}/\text{sq. in.}^2$ as indicated in the Register Book and in order that the working pressure can be determined, the Managers concerned should be requested to obtain a plan or sketch of the boilers.

Confirmation is required of the following:-

- (a) Diameter and pitch of rivet holes in longitudinal shell seams.
- (b) Thickness of shell plating
- (c) Thicknesses of combustion chamber top, side and back plates and pitch of the screwstays supporting these plates.

The sizes of the shafting as shown on the first Entry Report (San Francisco Oct No. 8608A) meet the requirements of the Rules.

Insufficient particulars are given regarding the pumping arrangements and a plan or sketch should also be requested.

Noted. Enquiry should be made of the M.O. regarding the Boilers & pumping arrangements. The future N.Y.K. should examine the details before sending the reports.

peak bulkhead to the deck next above the waterline (one second deck). According to the First Entry Report only 5 watertight

7.12.42

1710-696500-290500
005062-005469-0141