

Vessel towed to Auckland
after breakdown of turbine
machinery due to failure of
a lubricating oil pump.

Some turbine blades -
damaged - cut out &
bearings remounted.

Classing survey not
advanced.

It is submitted that
this vessel is eligible to
be recorded.

G.E. due 6.42

Pt due 6.42

Pt Shift
due 5.42

SA

16/7/42



© 2020

Lloyd's Register
Foundation