

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20<sup>th</sup> October 1911 When handed in at Local Office 10 Port of BUENOS AIRES  
 No. in Reg. Book 350 Survey held at on the Wood, Iron or Steel Tug "Larrea" Date, First Survey 19<sup>th</sup> Sept. Last Survey 14<sup>th</sup> October 1911  
 Master ✓

## TONNAGE:-

GROSS 132NET 126

5

Built at Goole By whom Goole S. B. & Repg. Co. Ltd.  
 Owners (Nicolai Michanovich) Ltd.

Port belonging to Buenos Aires

Owners' Address

(if not already recorded in Appendix to Register Book).

Laid Afloat or in Dry Dock ✓Name of Dock Government Drydock Destined Voyage Towing purposes.Cell DBorDBa

feet; uE&amp;B

feet; f

feet; f

capacity tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned Surveyed	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A 1 for Towing purposes 6.11		+ LMC 6.11

E. All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. 350 Port Goole

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from repairs due to other causes; repairs being detailed in the body of the report, should be summarised in the form shown below. Whenever the amount of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ✓

Where cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? Yes, see copy attached.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repairs of Damageaccount of being run into by the Dr. Blears in two.

Bulwark rail on the port side amidships, & two bulwark stanchions removed, faired, & refitted. Bulwark plates faired in place, the deck stringer faired & repaired in place, one scupper renewed & wood fender repaired, & minor repairs effected.

On account of damage, cause not stated. - The rudder removed, frame, plate, & rudder faired, riveted & replaced, top pintle renewed. The top gudgeon which was split, been satisfactorily repaired with the oxy-acetylene process.

On account of vessel falling off blocks in dry dock. - One shell plate in way of the main beam renewed, one shell plate removed, faired, & riveted in place, & one plate faired in place. one frame part renewed, 3 frames, the bulge keel, bulge stringer & casing angle all faired in place.

## OF DAMAGE REPAIRS:-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
ed	✓ 1	✓ 1 part						
and Faired or Repaired	✓ 1							1 length bulwark rail
or Repaired in place	✓ 1	✓ 3				1		2 bulwark plates

## CONDITION OF THE

Good	Stringers	Good	Dblg. Plates under Sounding Pipes	Good	Copper, or T.M. of Wood Vessels
"	Inner Bottom Plating	"	Engine Room Skylights	Good	(state if on Feet.)
"	State if Tanks have been examined inside	✓	Coal Bunkers, Open'gs, Lids, &c.	"	When put on, Month
"	State if Tanks now tested	✓	Scuppers	"	Boats
"	Bulkheads	Good	Cargo Hatchways	✓	Masts, Tacks, &c.
"	Ceiling	✓	Hatches	✓	Condition, how ascertained
"	Cement as Asphalt	Repaired	Planking of Wood Vessels	✓	(State if wedges removed)
"	Rudder	"	Caulking	ditto	Sails
"	Steering gear and its connections	"	Treenails	ditto	Equipment letter
"	Windlass	"	Breasthooks & Stems	ditto	Anchors, No. of
"	Have Pumps now been examined and found efficient?	✓	Transoms, Pointers, & Crutches ditto	✓	Cables (State if new ranged)
"	Have Sluice Valves now been examined and found efficient?	✓	Timbers of Frame at openings ditto	✓	" length size
"	Have Watertight Doors now been examined and found efficient?	✓	Ditto ditto at other places ditto	✓	" Rule length size
"			Stringers, Clamps & Shells ditto	✓	Rule length size
"			Salting ditto	✓	Hawser & Warps
"			(State if examined.)	✓	Standing & Running Rigging

## Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and ptnd09, &c."

vessel is eligible in my opinion to be continued as classed with fresh of survey 10.11 in the Register Book.

Repair Fee (if any) \$ 50.00

(if chargeable) \$ 8.00

Second Surveyor's Fee (if any) 2

Committee's Minute

Character Assigned

Fees applied for,

23.10.1911

Received by me,

19

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

TUE NOV. 21 1911

FRI MAY 9 1913

Lloyd's Register  
Foundation