

Shell plate B1 indented at upper landward

35 MAR 1946

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "VIC 79" REPORT Grk. No. 23243

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage. ~~Warfare~~

Subject to permanent repairs to indented shell plates B.1, D.1 and E.1 etc. (p.s.f) at the first convenient opportunity.

2.46 Grk.

CARGO BATTENS NOT FITTED.



© 2020 6.3.46.

Lloyd's Register Foundation

605 756-605 778-0288

ND 1

(p.s.f.) at first convenient opportunity.