

4 E

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

L'S NAME "PLADDA" REPORT Sng. No. 7550

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This case has been stated in previous endorsements.

The Singapore Surveyor now reports the installing of some electric cables in various parts of the vessel, but owing to the unsatisfactory nature of the work the survey has been left in abeyance until more definite arrangements can be made by the Owners.

IT IS SUBMITTED action be deferred.



© 2021

Lloyd's Register Foundation

5. 3. 48.

006954-006967-0234