

REPORT ON OIL ENGINE MACHINERY.

No. 20601

27 JAN 1942

Received at London Office

Date of writing Report 26/1/42 When handed in at Local Office 26/1/42 Port of Leith
 No. in Survey held at Leith Date, First Survey Aug 6th 1941 Last Survey 14th Jan 1942
 Reg. Book. Number of Visits 19

on the ~~Twin~~ ^{Single} ~~Triple~~ ^{Motor} ~~Quadruple~~ ^{TUG} "M.S.C. NEPTUNE".
 Screw ~~propeller~~

Tons { Gross 131.0
 Net 112

Built at Leith By whom built Henry Robb Ltd Yard No. 319 When built 1942
 Engines made at Manchester By whom made Crossley Bros Ltd Engines No. 127906 When made 1942
 Donkey Boilers made at ✓ By whom made ✓ Boiler No. ✓ When made ✓
 Brake Horse Power 440 ✓ Owners Manchester Ship Canal Co Port belonging to Manchester
 Nom. Horse Power as per Rule 240 27 Is Refrigerating Machinery fitted for cargo purposes ✓ Is Electric Light fitted Yes
 Trade for which vessel is intended Towing purposes on the Manchester Ship Canal.

IL ENGINES, &c.—Type of Engines ✓

2 or 4 stroke cycle ✓ Single or double acting ✓

Maximum pressure in cylinders ✓

Diameter of cylinders ✓

Length of stroke ✓

No. of cylinders ✓

No. of cranks ✓

Mean Indicated Pressure ✓

Span of bearings, adjacent to the Crank, measured from inner edge to inner edge ✓

Is there a bearing between each crank ✓

Revolutions per minute ✓

Flywheel dia. ✓

Means of ignition ✓

Kind of fuel used ✓

Crank Shaft, { Solid forged
Semi built
All builtdia. of journals as per Rule
as fitted ✓

Crank pin dia. ✓

Crank Webs ✓

Mid. length breadth ✓

shrunk

Thickness parallel to axis ✓

Thickness around eye-hole ✓

Flywheel Shaft, diameter as per Rule
as fitted ✓Intermediate Shafts, diameter as per Rule
as fitted ✓Thrust Shaft, diameter at collars as per Rule
as fitted ✓Tube Shaft, diameter as per Rule
as fitted ✓Screw Shaft, diameter as per Rule
as fitted ✓Is the { tube
screw } shaft fitted with a continuous liner { No liner ✓Bronze Liners, thickness in way of bushes as per Rule
as fitted ✓Thickness between bushes as per Rule
as fitted ✓

Is the after end of the shaft made watertight in the

propeller boss Yes ✓ If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner ✓

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive ✓

If two liners are fitted, is the shaft lapped or protected between the liners ✓

Is an approved Oil Gland or other appliance fitted at the after end of the tube

shaft Yes ✓ If so, state type Newark

Length of Bearing in Stern Bush next to and supporting propeller 1'-10 1/2" ✓

Propeller, dia. 6'-1 1/2" Pitch 3'-8" 6'-2" 11'-2"

No. of blades 4

Material Cast Iron

whether Moveable No

Total Developed Surface 18'-4" sq. feet

Method of reversing Engines ✓

Is a governor or other arrangement fitted to prevent racing of the engine when detached ✓

Means of lubrication

Thickness of cylinder liners ✓

Are the cylinders fitted with safety valves ✓

Are the exhaust pipes and silencers water cooled or lagged with

non-conducting material ✓ If the exhaust is led overboard near the waterline, what means are arranged to prevent water from being syphoned back to the engine up funnel

Cooling Water Pumps, No. one each engine ✓

Is the sea suction provided with an efficient strainer which can be cleared within the vessel ✓

Bilge Pumps worked from the Main Engines, No. 1 each engine

Diameter Capacity Stroke 3500 galls per hour

Can one be overhauled while the other is at work ✓

Pumps connected to the Main Bilge Line { No. and Size 1 off - Centrifugal Type

How driven Electric Motor Capacity 20 tons per hour.

Is the cooling water led to the bilges No

If so, state what special arrangements are made to deal with this water in addition to the ordinary bilge pumping arrangements ✓

Ballast Pumps, No. and size 1 Motor driven Centrifugal Capacity 20 tons per hour

Power Driven Lubricating Oil Pumps, including Spare Pump, No. and size 2 each engine Capacity 235 galls per hour

Are two independent means arranged for circulating water through the Oil Cooler + Main Engs. Yes ✓

Suctions, connected to both Main Bilge Pumps and Auxiliary Bilge

Pumps, No. and size:—In Machinery Spaces 1-2" dia aft ✓

In Pump Room

In Holds, &c. Fore Compartment 1-2" dia ✓

Independent Power Pump Direct Suctions to the Engine Room Bilges, No. and size 1-2" port, 1-2" starboard, led to pumps driven by Aux Engines.

Are all the Bilge Suction pipes in Holds and Tunnel Well fitted with strum-boxes Yes

Are the Bilge Suctions in the Machinery Spaces

led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges Yes

Are all Sea Connections fitted direct on the skin of the ship Yes

Are they fitted with Valves or Cocks Both

Are they fixed sufficiently high on the ship's side to be seen without lifting the platform plates Yes

Are the Overboard Discharges above or below the deep water line Above

Are they each fitted with a Discharge Valve always accessible on the plating of the vessel Yes

Are the Blow Off Cocks fitted with a spigot and brass covering plate ✓

What pipes pass through the bunkers None

How are they protected ✓

What pipes pass through the deep tanks None

Have they been tested as per Rule ✓

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times Yes

Is the arrangement of valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one

compartment to another Yes

Is the Shaft Tunnel watertight None

Is it fitted with a watertight door ✓

worked from

If a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork ✓

Main Air Compressors, No. ✓

No. of stages ✓

Diameters ✓

Stroke ✓

Driven by ✓

Auxiliary Air Compressors, No. ✓

No. of stages ✓

Diameters ✓

Stroke ✓

Driven by ✓

Small Auxiliary Air Compressors, No. ✓

No. of stages ✓

Diameters ✓

Stroke ✓

Driven by ✓

What provision is made for first Charging the Air Receivers

Scavenging Air Pumps, No. ✓

Diameter ✓

Stroke ✓

Driven by ✓

Auxiliary Engines crank shafts, diameter as per Rule
as fitted ✓

No. 2

Position 1 Port + 1 Starboard

Have the Auxiliary Engines been constructed under special survey ✓

Is a report sent herewith See Mch Repts 10674-75 ✓

AIR RECEIVERS:—Have they been made under survey ✓

State No. of Report or Certificate ✓

Is each receiver, which can be isolated, fitted with a safety valve as per Rule ✓

Can the internal surfaces of the receivers be examined and cleaned ✓

Is a drain fitted at the lowest part of each receiver ✓

Injection Air Receivers, No. ✓

Cubic capacity of each ✓

Internal diameter ✓

thickness ✓

Seamless, lap welded or riveted longitudinal joint ✓

Range of tensile strength ✓

Working pressure by Rules ✓

Actual ✓

Starting Air Receivers, No. ✓

Total cubic capacity ✓

Internal diameter ✓

thickness ✓

Seamless, lap welded or riveted longitudinal joint ✓

Material ✓

Range of tensile strength ✓

Working pressure by Rules ✓

Actual ✓

IS A DONKEY BOILER FITTED? No ✓

If so, is a report now forwarded? ✓

Is the donkey boiler intended to be used for domestic purposes only ✓

PLANS. Are approved plans forwarded herewith for Shafting & Sterngear ✓ Receivers ✓

(If not, state date of approval)

Separate Fuel Tanks ✓

Donkey Boilers ✓

General Pumping Arrangements With hull report

Pumping Arrangements in Machinery Space ✓

Oil Fuel Burning Arrangements ✓

SPARE GEAR.

Has the spare gear required by the Rules been supplied ✓

State the principal additional spare gear supplied ✓

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building { During progress of work in shops -- 1941.
During erection on board vessel -- Aug 6-26. Sept 5-11. Oct 1-6-7-20-30. Nov 13-24-26. Dec 11-16-19. Jan 1942. 2-9-13-14.
Total No. of visits On board 19. In Shops 13. Total 32.

Dates of Examination of principal parts—Cylinders ✓ Covers ✓ Pistons ✓ Rods ✓ Connecting rods ✓
Crank shaft ✓ Flywheel shaft ✓ Thrust shaft ✓ Intermediate shafts ✓ Tube shaft ✓
Screw shaft ✓ Propeller 6/10/41 Stern tube 3.5.11/9/41 Engine seatings 30/10/41 Engines holding down bolts 24/11/41
Completion of fitting sea connections 6/10/41 Completion of pumping arrangements 9/1/42 Engines tried under working conditions 13/1/42
Crank shaft, Material ✓ Identification Mark ✓ Flywheel shaft, Material ✓ Identification Mark ✓
Thrust shaft, Material ✓ Identification Mark ✓ Intermediate shafts, Material Steel Identification Marks ✓
Tube shaft, Material ✓ Identification Mark ✓ Screw shaft, Material Steel Identification Mark ✓
Identification Marks on Air Receivers See Mch Rept No 10720.

Is the flash point of the oil to be used over 150° F. ✓

Have the requirements of the Rules for oil fuel pipes and tank fittings been complied with ✓

Is the vessel (not being an oil tanker) fitted for carrying oil as cargo No

If so, have the requirements of the Rules been complied with ✓

If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with

Is this machinery duplicate of a previous case ✓ If so, state name of vessel M.S.C. Mallard & Merlin.

General Remarks (State quality of workmanship, opinions as to class, &c.)

This Machinery—Mch Rept 10720 on the Main Engines and Mch Rept 10674/5 on the Aux Engines has been efficiently fitted on board, the Materials & workmanship being sound & good. The Main & Auxiliary Machinery was tried in dock under full working conditions and found satisfactory in all respects. Manoeuvring tests were carried out and the capacity of the air receivers was found to be in excess of Rule requirements. The Auxiliary engines which drive the compressors can be started by hand.

In my opinion the Machinery of this Vessel is eligible to be classed in the Register Book with the notation of +LMC 1.42 and the records of Oil Engine: T.S.O.G.

The amount of Entry Fee .. £ : : When applied for,
Special 1/3 LMC... £ 21 : 18.6 26-1- 1942.
Donkey Boiler Fee ... £ : : When received,
Travelling Expenses (if any) £ : : 19

Committee's Minute

WED. 4 FEB 1942

Assigned

+Lmb 1.42
oil Lf.

L.B. Murray.

Engineer Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation