

REPORT ON BOILERS.

No. 18413

9 AUG 1943

Received at London Office

18 MAY 1943

Date of writing Report 17/5/1943 When handed in at Local Office 17/5/1943 Port of WEST HARTLEPOOL

No. in Survey held at WEST HARTLEPOOL

Date, First Survey 3rd November, 1942 Last Survey 5th May 1943

on the Steel Single Screw Rescue Tug "ANTIC"

(Number of Visits 10) Gross 597 Tons Net 1

Built at Selby By whom built Cochran & Sons, L^{td}.

Yard No. 1264 When built 1943

Engines made at HULL

By whom made MESS^{rs} C. D. HOLMES & CO.

Engine No. When made

Boilers made at WEST HARTLEPOOL

By whom made CENTRAL MARINE ENGINE WORKS.

Boiler No. R360 When made 1943.

Nominal Horse Power

Owners

Port belonging to

MULTITUBULAR BOILERS MAIN, AUXILIARY, OR DONKEY.

Manufacturers of Steel

Mess^{rs} Colvilles & Co. Glasgow.

(Letter for Record S.

Total Heating Surface of Boilers

3550 sq

Is forced draught fitted YES

Coal or Oil fired OIL.

No. and Description of Boilers

1 Single ended multitubular

Working Pressure 210 lbs.

Tested by hydraulic pressure to 365 lbs.

Date of test 12.5.43

No. of Certificate 4,000

Can each boiler be worked separately

Area of Firegrate in each Boiler

OIL FIRED.

No. and Description of safety valves to each boiler

Two spring loaded

Area of each set of valves per boiler

per Rule 16.14 sq in 19.72

as fitted 16.59

Pressure to which they are adjusted 213 lb

Are they fitted with easing gear YES

In case of donkey boilers, state whether steam from main boilers can enter the donkey boiler

✓

Smallest distance between boilers or uptakes and bunkers or woodwork

2'0"

Is oil fuel carried in the double bottom under boilers NO

Smallest distance between shell of boiler and tank top plating

NONE

Is the bottom of the boiler insulated PART

Largest internal dia. of boilers

17'0"

Length

11'6"

Shell plates: Material

Steel

Tensile strength 31-55 tons

Thickness

1 15/32"

Are the shell plates welded or flanged

No.

Description of riveting: circ. seams

end DR. LAP.

Long. seams TR Double butt straps

Diameter of rivet holes in

circ. seams 1 1/16"

long. seams 1 1/32"

Pitch of rivets

3 1/4"

10 1/2"

Percentage of strength of circ. end seams

plate 62.2

rivets 43.

Percentage of strength of circ. intermediate seam

plate -

rivets -

Percentage of strength of longitudinal joint

plate 84.8.

rivets 86.7.

Thickness of butt straps

outer 1 1/8"

inner 1 1/4"

No. and Description of Furnaces in each Boiler

3 Corrugated Deighton section

Material

Steel

Tensile strength

26-30 tons

Smallest outside diameter

4'3 1/2"

Length of plain part

top -

bottom -

Thickness of plates

crown 3/4"

bottom 3/4"

Description of longitudinal joint

Welded.

Dimensions of stiffening rings on furnace or e.c. bottom

Shell plates in steam space: Material

Steel

Tensile strength

26-30 tons

Thickness

1 3/16"

Pitch of stays 20 3/4 x 16"

How are stays secured

Double nuts and washers.

Fire plates: Material

front Steel

back Steel

Tensile strength

26-30 tons

Thickness

15/16"

29/32"

Pitch of stay tubes in nests

10 5/8 x 8 1/2"

Pitch across wide water spaces

13 1/2"

Girders to combustion chamber tops: Material

Steel

Tensile strength

29-33 tons

Depth and thickness of girder

Centre 9 x 1 3/4, 2 3/8 plates length as per Rule

2'8 3/32"

Distance apart

9 3/4"

No. and pitch of stays

Each 3 @ 7 3/4"

Combustion chamber plates: Material

Steel

Tensile strength

26-30 tons

Thickness: Sides

23/32"

Back

23/32"

Top

1 1/16"

Bottom

7/16"

Pitch of stays to ditto: Sides

10 x 8 1/2"

Back

9 1/2 x 8 3/8"

Top

9 3/4 x 7 3/4"

Are stays fitted with nuts or riveted over

nuts

Bottom plate at bottom: Material

Steel

Tensile strength

26-30 tons

Thickness

15/16"

Lower back plate: Material

Steel

Tensile strength

26-30 tons

Thickness

27/32"

Pitch of stays at wide water space

13 3/4 x 8 3/8"

Are stays fitted with nuts or riveted over

nuts

Shipping stays: Material

Steel

Tensile strength

28-32 tons

Pitch of stays: At body of stay,

3 1/8"

No. of threads per inch


6

Pitch of stays: At turned off part,

1 3/4"

No. of threads per inch

9.



© 2020

Lloyd's Register Foundation

007396-007402-0232

Are the stays drilled at the outer ends No. Margin stays: Diameter ^{At turned off part,} 2" or ^{Over threads}
No. of threads per inch 9.
Tubes: Material L.W. IRON. External diameter ^{Plain} 3" ^{Stay} 3" Thickness 8WG 5/16" 3/8" 7/16" No. of threads per inch 9.
Pitch of tubes 2 1/4" x 2 1/4" Manhole compensation: Size of opening
shell plate 16 x 12" Section of compensating ring 3'0" x 2'4 1/2" x 1 1/2" No. of rivets and diameter of rivet holes 32 @ 1 1/2"
Outer row rivet pitch at ends 10 1/16" Depth of flange if manhole flanged -A- Steam Dome: Material None.
Tensile strength Thickness of shell Description of longitudinal joint
Diameter of rivet holes Pitch of rivets Percentage of strength of joint ^{Plate} ^{Rivets}
Internal diameter Thickness of crown No. and diameter
stays Inner radius of crown
How connected to shell Size of doubling plate under dome Diameter of rivet holes and pitch
of rivets in outer row in dome connection to shell

Type of Superheater NONE. Manufacturers of ^{Tubes} ^{Steel forgings} ^{Steel castings}
Number of elements Material of tubes Internal diameter and thickness of tubes
Material of headers Tensile strength Thickness Can the superheater be shut off and
the boiler be worked separately Is a safety valve fitted to every part of the superheater which can be shut off from the boiler
Area of each safety valve Are the safety valves fitted with easing gear
Pressure to which the safety valves are adjusted Hydraulic test pressure
tubes forgings and castings and after assembly in place Are drain cocks
valves fitted to free the superheater from water where necessary
Have all the requirements of Sections 14 to 22 inclusive for boilers been complied with YES

The foregoing is a correct description,
FOR THE CENTRAL MARINE ENGINE WORKS
(Ld. Eng. & Sh. Engrs.)

Dates of Survey ^{During progress of} ^{work in shops - -} 1942 - Nov 3 - 1943 - Mar. 16 - 18 - 21 - Apr 12 - 20 - 27 - May 3 - 4 - 5 Are the approved plans of boiler and superheater forwarded herewith YES
^{while} ^{building} ^{During erection on} ^{board vessel - -} YES Total No. of visits 10

Is this Boiler a duplicate of a previous case Yes. If so, state Vessel's name and Report No. R359. RAN. 18394.

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.) This boiler has been constructed under special survey and in accordance with the approved plan for a working pressure of 210 lbs per square inch.
The materials and workmanship have been found good.
Upon completion the boiler was tested in the presence of the undersigned by a hydraulic pressure of 365 lbs per square inch showed no signs of weakness and was found tight and sound in every respect at that pressure.
It has now been despatched to Hull for fitting on board.

[The above boiler installed on board "ANTIC" at Hull, safety valves adjusted as above, accumulation test held and afterwards examined on completion of all tests. L.S. Shields.

Survey Fee ... £ 23 : 14 : 0 When applied for, 17/5/ 1943
Travelling Expenses (if any) £ : : When received, 19

Arthur W. Oxford.
Engineer Surveyor to Lloyd's Register of Shipping

Committee's Minute TUES. 17 AUG 1943

Assigned see minute on Hull I.E. Rpt.



© 2020

Lloyd's Register
Foundation