

19159 in RB

20 SEP. 1921

Chief Surveyors 15.9.21

Received from Chief Surveyors _____

VESSEL'S NAME SH. M. V. "Indovita"

Report PE. Liv No. 87858

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

of Survey _____

When due _____

This vessel's class is continued subject to an independent bilge & ballast pump being satisfactorily fitted on board.

In reply to an enquiry as to whether this had been done, the Owners now state that they cannot see their way at present to fit an auxiliary pump on this vessel & they will be obliged if the matter of the classification of the machinery can be held up for the moment. It is submitted action be deferred for a short time.



© 2021

Lloyd's Register
Foundation

007439-007447-0089