

REPORT of SURVEY for REPAIRS, &c

Date of writing Report 2/7/40. When handed in at Local Office 3rd July 1940 Port of Kobe

No. in Reg. Book. Survey held at Harima. Date, First Survey 1/6/40 Last Survey 26/6/1940.

2544-26287 on the ~~Wood~~ ~~from~~ Steel T.M.S. "HUKKO MARU".TONNAGE:- Built at Harima. By whom Kobe Steel Works, Ltd. When 1924 12
GROSS 3834 Owners Hukko Syosen K.K. Owners' Address
UNDER DEK. 3385 Managers Taiyo Kaiun K.K. (if not already recorded in Appendix to Register Book).
NET 2290 Port belonging to Hasidate.

Surveyed Afloat or in Dry Dock? Both Name of Dock Harima Dock. Destined Voyage

B=Cell DBorDBa feet; uE&B feet; f feet
tal capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 108 00. Port Kob.

Periodical Surveys, when held, must be reported in detail and in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	Year	Machinery and Boiler
* for Special Survey.	Surveyed	Surveys
Date of last Survey and of Periodical Surveys.	how	(including date of N.B., if any)
	examined	
*100A1	8,38	*LMC (CS) 7,36
		8,38
		DES 8,38
		TS (CL) P. 8,38
		S. 7,36

ssKob. No. 3-7,36.

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR PART SPECIAL SURVEY 2nd No.1.

NOW DONE:- Vessel placed in dry dock. Hull, bottom, rudder (lifted) stern frame, propeller brackets, and stem cleaned, examined and found or now placed in good condition, afterwards recoated.

Holds, fore and after peaks, and chain locker, spaces under bridge, engine space cleared for survey, ceiling lifted as required by rules, all oxidation removed and steel work throughout carefully examined and found or now placed in good condition, afterwards recoated.

Lining on ship's side removed in way of sidelights and plating in way of same examined in good condition.

Nos. 1, 2, 3 & 5 double bottom tanks, deep tanks and fore and after peak tanks examined internally, found or now placed in good condition, afterwards recoated and tested with a head of water as required by the rules, and found tight. (P.T.O.).

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

As/Rpt.

cks	Good	State if Tanks have been examined inside	Yes/	Air and Sounding Pipes	As/Rpt. Good	Copper, or Y.M. of Wood Vessels	--
ulking of Decks	"	State if Tanks now tested	Yes, As/Rpt.	Dblng. Plates under Sounding Pipes	"	(State if on Felt).	--
amings	"	Bulkheads	Good	Engine Room Skylights	Good	When put on, Month	-- Year --
ams & Fastenings	"	Ceiling	"	Coal Bunkers, Open'gs, Lids, &c.	--	Boats	Good
tside Plating	"	Cement	As/Rpt. Good	Oil Bunkers	Good	Masts, Yards, &c.	"
" in way of sidelights	"	Rudder	Good	Scuppers	"	Condition, how ascertained	From aloft.
asthooks	"	Steering gear and its connections	"	Cargo Hatchways	"	(State if wedges removed)	--
ansoms	"	Windlass	"	Hatches	"	Sails	--
ames	"	Have pumps now been examined and found efficient?	Yes.	Planking of Wood Vessels	--	Equipment letter	N
verse Frames	"	Have Sluice Valves now been examined and found efficient?	--	Caulking	ditto	Anchors, No. of	3B. 1s.1k.
ngitudinals	--	Have Watertight Doors now been examined and found efficient?	Yes.	Treenails	ditto	Chain Locker	Good
ansverses	--	Have Ventilators and their Coamings been examined and found efficient?	Yes.	Breasthooks & Stemson	ditto	Cables (State if now ranged)	Yes.
ors	As/Rpt. Good			Transoms Pointers, & Crutches	ditto	" length (on board)	270 fms. mean diamr. 2 1/2"
elsons	"			Timbers of Frame at openings	ditto	" Rule length	size 16
ringers	"			Ditto Ditto at other places	ditto	Hawser & Warps	Good
ner Bottom Plating	"			Stringers, Clamps & Shefts	ditto	Standing and Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is in good condition and eligible, in my opinion, to be continued as classed, with fresh record of survey 6,40 and to have the Notation S.S. Kob. 2nd No.1-40 when the Special Survey has been completed.

Survey Fee (per Section 20) Yen 275:00

Special Damage or Repair Fee (if any) --

Travelling Expenses (if chargeable) Yen 96:00

(Including Machinery).

Second Surveyor's Fee (if any) E

Fees applied for, 1/7/1940

Received by me, 19

Surveyor to Lloyd's Register of Shipping.

FRI. 15 MAY 1942

OMIT CLASS ON RE-PRINT.

Lloyd's Register Foundation

007679-007687-0239

May [

No.4 double bottom tank and fore and aft oil fuel settling tanks, between tunnels, to be examined internally. + tested

REPAIRS DUE TO WEAR AND TEAR:-

Other minor repairs carried out. *B.A.*

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

This Certificate is to be executed, it is to be whatever to be in the Registry in the Reg Committees or a

B.) -10m,5,38. (MA)