

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office MON. 5 DEC 1910)

Date of writing Report 1 December 1910 When handed in at Local Office 19

Port of Amsterdam

No. in Reg. Book. Survey held at Amsterdam

Date, First Survey 11 August

Last Survey 26 November 1910

(No. of Visits 13.)

Yl in Chapp on the Machinery of the Wood, Iron or Steel Vessel Cornelis

Master J. W. Rorling

YEAR. MONTH.

Tonnage Gross 399 Net 235

Vessel built at Galt Bommel By whom J. Meijer's Shipbuilding Co When 1910 - 10

Registered Horse Power

Engines made at Amsterdam

By whom Ned Fabrick van Werkhuizen When 1910

No. of Main Boilers

Boilers, when made (Main)

(Donkey)

No. of Donkey Boilers

Owners J. Van Rompen

Port Terneuzen

Voyage United Kingdom

Steam Pressure in Main Boilers

If Surveyed Afloat or in Dry Dock Afloat

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.

Year Assigned now expired

Machinery and Boiler Surveys (including date of N.B., if any).

100 A

Contemplated

Last Report No. Port

Particulars of Examination and Repairs (if any) Building fitting on board

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? or is it without liners?

Has shaft now been changed? If so, state reasons

Is the shaft now fitted new? Yes Has it a continuous liner? Yes or two liners? or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined this vessel's shafting and seal connections fitted whilst vessel in Course of Construction in Builder's Yard. Pipe arrangement fitted in accordance with the Society's rules and approved plan herewith returned to London Office Inspected the fitting of motor and auxiliaries and attended to trial trip. Motor working satisfactory proved to be well secured on its seat.

As this vessel's machinery is not classed, it is submitted that no further action be taken in the case

Wk for Register Book. Particulars of Motor.

General Observations, Opinion, and Recommendation:—

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,00, B.&H.S. 9,00, or L.M.C. 9,00, 140 lb., F.D., &c.)

For the Committee's information.

4.S.C.S.A

Oil Engine.

4 Cy 12 9/16 - 16 1/2

Ned. Fabrick van Werkhuizen, Ams

Survey Fee (per Section 28).....

£ 24.-

Fees applied for

19

Special Damage or Repair Fee (if any).....

£

Received by me,

19

Travelling Expenses (if chargeable).....

£ 20.15

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUE. 6 DEC 1910

Assigned

no action

note oil engine re

007988-007997-0196