

24 JAN 1939

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

TENRYO MARY.

Rpt.

Shm

No. 2421

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

Damage through

collision

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Removed and faired } or repaired..... }	1	2					
Faired or repaired } in place..... }	5						

Other items:-

vessel placed in dry dock.

Bottom coated.

Stem faired and minor repairs effected.

It is submitted the vessel is worthy to remain as classed without record of Survey as recommended.



© 2021

Lloyd's Register Foundation

008158-008167-0134