

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 22620

Date of writing Report 24th June 1947 When handed in at Local Office 25th June 1947 (Received at London Office 18 JUL 1947)
 No. in Reg. Book. 15013 Survey held at Grimsey Date, First Survey 29th May Last Survey 24th June 1947
 on the Machinery of the Steel K "BELLONA" (No. of Visits four)
 Tonnage } Gross 184 Vessel built at Selly By whom Cochrane Sons
 Net 88 Engines made at Hull By whom C. D. Holmes 16th When 1907-11
 Nominal Horse Power 57 HP Boilers, when made (Main) 1932 (Donkey) 1907
 No. of Main Boilers 1-52 Owners Consolidated Fisheries Ltd Owners' Address (if not already recorded in Appendix to Register Book.)
 No. of Donkey Boilers ✓ Managers Sir John D. Marsden, Bt. Port Grimsey Voyage ✓
 Team Pressure in Main Boilers 180 lbs. Surveyed Afloat ✓ in Dry Dock Nº 3 Dry Dock + Fish Dock
 in Donkey Boilers ✓ (State name of Dock.)

Last Report No. PortParticulars of Examination and Repairs (if any) Cond + B.S

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

as a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside Cond + B.S Boiler Cond + B.S and make a thorough examination at this time? yes

" " Donkey " " " " " " " " " " " "

Was this not done, state for what reasons? ✓

What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

What latest date of internal examination of Cond + B.S boiler 13th June 1947

Did the Surveyor examine the Safety Valves of the Cond + B.S Boiler? yes

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Cond + B.S Boilers? yes

Did the Surveyor examine the drain plugs of the Cond + B.S Boilers? none fitted

Did the Surveyor examine all the mountings of the Cond + B.S Boilers? yes

Has screw shaft now been drawn and examined? no

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

What date of examination of Screw Shaft ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Afloat

Engine parts, when referred to by numbers, should be counted from forward.

Did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Is Survey not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now done:- Vessel placed in dry dock. Propeller, outside fastenings examined and found in order.

Boiler examined internally and externally, safety valves, mountings, manhole doors and found same in good order; later examined boiler under steam and adjusted the safety valves as above.

NOTE The following machinery has been opened out: working parts examined and found in good order:- Cylinders, pistons, slide valves, steam chest; crank and thrust bearing.

General Observations, Opinion, and Recommendation:- The machinery is in good & efficient state clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, L.S. 9, 11, B.S. 9, 11, B.S. 9, 11, or L.M.C. 9, 11, or

Classification and eligible, in my opinion to remain as classed with a fresh record of S. 6.47.

Fee (per Section 29) BS £ 3 : 0 : 0

Damage or Repair Fee (if any) (per Section 29.) £ :

Expenses (if chargeable) £ :

Fees applied for 30-6-1947
Received by me, 19

Committee's Minute

ned

FRI. 1 AUG 1947

Deferred for MS.

As now subject

BS 6,47

G. B. Vaux
Engineer Surveyor to Lloyd's Register of Shipping.

The door is welded to the steam pipe
been examined internally.

B.S. due 6.47 would

Some main engine parts examined.

It is submitted that this vessel is eligible for THE

RECORD. B.S. 6-47.

Signed as above

5.

30-7-47-

25 JUL 1947

© 2021

Lloyd's Register
Foundation