

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in oil.

Is an approved oil

# "Cité de Québec"

Ch. 50721

It is submitted that  
this vessel is eligible for  
**THE RECORD + LMC 9.30**

C-L. FD.

Subject to the float tank seating of monotype air  
pumps being made permanent.

Pl. 17/9/30.

It is concluded that (as in the case of  
the sister ship *Cité de Lévis*) the area of  
safety valve given in the boiler report (Chs 50566)  
refers to one valve only.



Lloyd's Register  
Foundation

IS A DONKEY BOILER FITTED?

no.

008993-009003-0250

If so, is a report now forward