

height extended at the Dinges
" Intercostal Plate for length ✓
" Attached to outside Plating with Angle ... ✓

009287-009300-0125

3m.224.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *S. S. dredger M. S. C. Gowy* Report *Gls.* No. *43869*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Time of Survey *1st Entry* When due *(Revised Rules)*

+ 100A1 (Steel) "Dredger"
IDK (steel.)
F.K. 5 B.H. Sem. Lloyds A.V.C.P. F15'



31.7.74
Lloyd's Register
Foundation

The Surveyors should be requested to forward the foregoing reports.

Bridge Deck, Angle, Bulb Angle, Plate,)

Deck, Material and thickness