

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report: 29/10/40 When handed in at Local Office: 30th Oct 1940 Port of Kobe. No. 4645
 No. in Reg. Book. Survey held at Kobe. Date, First Survey 14/10/40. Last Survey 28/10/1940.
 (No. of Visits Five.)

7111 on the ~~WOODS~~ ~~IRON~~ ~~STEEL~~ M.S. "CANBERRA MARU".
 TONNAGE:— Built at Tama. By whom Mitsui Bussan Kaisha, Ltd. When 1938 6
 GROSS 6477 Owners Osaka Syosen Kabusiki Kaisya. Owners' Address
 UNDER DEK 5837 Managers Port belonging to Osaka.
 3858

ed Afloat or in Dry Dock? Both Name of Dock Mitsubishi Dock. Destined Voyage

ell/D BorDBa feet; uE&B feet; f feet
 capacity tons. FPT tons; APT tons; MT feet tons.

All alterations in the existing records should be underlined.

Report, No. 11191. Port Kob.

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to be the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters in this case.

re cases where the Surveyor has not made a special damage report he is required to state whether he his services for this purpose and to whom and why they were declined --

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned expired.	Machinery and Boiler Surveys (including date of N.B., in any).
*100A1	7,39	*LMC 5,36
with freeboard.		*Lloyd's RMC 12,40
		TS (CL) 7,39

Society's Freeboard (if assigned) as 3320 m/m.
 painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom? --

S. OR EXAMINATION AS PER RULE, FOR SPECIAL SURVEY No.1.

NE:- Vessel placed in dry dock. Hull, bottom, rudder, stern frame and stem cleaned, ed and found or now placed in good condition, afterwards recoated.

Holds, tween decks, fore and after peaks, and chain locker, spaces under brige, engine iler space cleared for survey, ceiling lifted as required by rules, oxidation removed from rts, and steel work throughout all parts of the vessel carefully examined and found or now in good condition, afterwards recoated.

Double bottom tanks, fore and after peak tanks examined internally, found or now placed d condition, afterwards recoated and tested with a head of water as required by the rules, and tight.

(P.T.O.).

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
ed								
ed and Faired or Repaired								
or Repaired in place								

CONDITION OF THE	Good	State if Tanks have been examined inside	Yes.	Air and Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels	--
ecks	"	State if Tanks now tested	Yes.	Dblng. Plates under Sounding Pipes	"	(State if on Fett.)	--
enings	"	Bulkheads	Good	Engine Room Skylights	"	When put on, Month	--
g	"	Ceiling	"	Coal Bunkers, Open'gs, Lids, &c.	--	Boats	Good
n way of sidelights	--	Cement XXXXXX	"	Oil Bunkers	--	Masts, Yards, &c.	"
	Good	(State which.)	"	Scuppers	Good	Condition, how ascertained	From aloft.
	"	Rudder	"	Cargo Hatchways	"	(State if wedges removed)	--
	"	Steering gear and its connections	"	Hatches	"	Sails	--
	"	Windlass	"	Planking of Wood Vessels	--	Equipment letter	67
	"	Have pumps now been examined and found effi-	Yes.	Caulking	ditto	Anchors, No. of	3B. 1S.
	--	cient?	Yes.	Treenails	ditto	Chain Locker	Good
	--	Have Sluice Valves now been examined and found	--	Breasthooks & Stemson	ditto	Cables (State if now ranged)	Yes.
	Good	efficient?	--	Transoms Pointers, & Crutches	ditto	" length 315 ^g fms mean diam. 2 ^g "	
	"	Have Watertight Doors now been examined and found	Yes.	Timbers of Frame at openings	ditto	" (on board)	100 size 2 ^g
	"	efficient?	Yes.	Ditto Ditto at other places	ditto	" Rule length	100 size 2 ^g
	"	Have Ventilators and their Coamings been examined	Yes.	Stringers, Clamps & Shells	ditto	Hawser & Warps	Good
Plating	"	and found efficient?	Yes.	Salting	ditto	Standing and Running Rigging	"

Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24.

This vessel is in good condition and eligible, in our opinion, to be continued as classed with fresh record of survey 10,40 and the Notation S.S.Kob.No.1-40.

Survey Fee (per Section 29) Yen 275:00 : Fees applied for, 28/10/1940
 Special Damage or Repair Fee (if any) -- :
 Travelling Expenses (if chargeable) Yen 23:00 : Received by me, 19
 (Including Machinery)
 Second Surveyor's Fee (if any) £

Committee's Minute

Character Assigned

FRI. 23 MAR. 1941

Surveyor to Lloyd's Register of Shipping.

TUE. 12 MAY 1942

OMIT CLASS ON RE-PRINT.

Lloyd's Register Foundation

Freeboard verified.

REPAIRS DUE TO WEAR AND TEAR:-

Minor repairs effected.

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

