

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

MAY 16 1938

Date of writing Report 12-4-1938 When handed in at Local Office 12/4/1938 Port of YOKOHAMA

No. in Reg. Book 34632 Survey held at YOKOHAMA Date, First Survey 14-3 Last Survey 5-4-1938 (No. of Visits Three)

on the Machinery of the Wood, Iron or Steel S.S. "TAIAN MARU" Ex. "TAAN"

Tonnage { Gross 5411 Vessel built at Montreal By whom Canadian Vickers Ltd. When 1921-5  
Net 3848 Engines made at Do. By whom Do. When 1921

Nominal Horse Power 520 Boilers, when made (Main) 1921. (Donkey)

No. of Main Boilers 3 SB Owners AMAKASU GOMEI KAISHA Owners' Address 32, 3-CHOME MASAGO-CHO, NAKA-KU, YOKOHAMA.

No. of Donkey Boilers ✓ Managers ✓ Port YOKOHAMA Voyage YOKOHAMA.

Steam Pressure in Main Boilers 180 lbs. If Surveyed Afloat or in Dry Dock afloat & dry dock Yokohama Dock.

in Donkey Boilers ✓ Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) LMC. Elect. fitting.

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined \_\_\_\_\_

Was a damage report made by anyone else? If so, by whom? \_\_\_\_\_

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " " \_\_\_\_\_

If this was not done, state for what reasons? \_\_\_\_\_

And what parts of the Boilers could not be thus thoroughly examined? \_\_\_\_\_

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? \_\_\_\_\_

State latest date of internal examination of each boiler all - 14/3/38Present condition of funnel good.Did the Surveyor examine the Safety Valves of the Main Boiler? YesTo what pressure were they afterwards adjusted under steam? 180 lbs.Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓To what pressure were they afterwards adjusted under steam? ✓Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? ✓Did the Surveyor examine the drain plugs of the Main Boilers? ✓, and of the Donkey Boiler? ✓Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boiler? ✓Has screw shaft now been drawn and examined? ✓Is it fitted with continuous liner? ✓Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓Has shaft now been changed? ✓ If so, state reasons \_\_\_\_\_Has the shaft now fitted been previously used? ✓Has it a continuous liner? ✓Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓State date of examination of Screw Shaft 8.36State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/16"

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? Yes.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done \_\_\_\_\_

Complete.

Now done: - Vessel placed in dry dock, propeller, aft end of stern bush, sea cocks and valves with their shell fastenings examined and found in order.

Main engine cylinders, slide valve casings, pistons, rods, crosses, crank, thrust and tunnel shafting, condenser, pumps, piping and pumping arrangements examined. Dynamo engine, cylinder, crank throughout, generator, bearing, main switch board with all electric installations examined, tested by Megger and found or now placed in good conditions.

The three main boilers examined throughout with all the mountings and doors, all the main steam pipes water tested by hyd. press to 360 lbs per sq. in. and found in order.

Repairs due to wear & tear: Main engine piston packing rings renewed. Aux condenser tubes renewed. 7 main cylinders renewed. (Continued)

General Observations, Opinion, and Recommendation: - The Boilers and the machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, L.M.C. 9, 11, or L.M.C. 140 lb., F.D., &c.)

of this vessel are in good condition and eligible in my opinion to remain as classed with fresh record of + LMC 4.38.

Survey Fee (per Section 29) ¥ 260<sup>00</sup> Fees applied for 6-4-1938  
Special Damage or Repair Fee (if any) \_\_\_\_\_  
(per Section 29.) \_\_\_\_\_  
Travelling expenses (if chargeable) ¥ 1<sup>00</sup> Received by me 7-4-1938

Committee's Minute FRI. 27 MAY 1938Assigned + LMC 4.38

CERTIFICATE WRITTEN.

R. Kibigami  
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
Foundation

009493-009504-0310 1/2



## "TAIAN MARU"

Some amount of deformation found on Port & starboard main boiler furnaces. Port boiler furnaces  $1\frac{3}{8}"$  or  $1\frac{1}{16}"$ , Center boiler furnaces  $1"$ , Starboard boiler furnaces  $1\frac{3}{16}"$ . It was stated by the Owner, that these furnaces will be jacked up at the Owner's convenience.

Note:- A sketch of the present main boilers was taken by the owner, which will be sent together with this report for your reference. The Owner changed. Ship's name and Port of Registry changed as underlined.

RA



*E.O. examined*

It is submitted that  
this vessel is eligible for  
THE RECORD *HLUC 4-38*

*GA*  
*1917-38*

*Handwritten text, likely bleed-through from the reverse side of the page. The text is written in cursive and is mostly illegible due to fading and the angle of the page. It appears to be a list or a series of entries, possibly related to the vessel's history or the records mentioned in the printed text.*

"USNA VNAI"



© 2020

Lloyd's Register  
Foundation