

Rpt. 8.

DISCLOSED SECTION REPORT of SURVEY for REPAIRS, & C.

Date of writing Report 19... When handed in at Local Office 10... Port of London

No. in Reg. Book 52679 Survey held at on the Wood Iron or Steel "M.S.C. GAMMA"

TONNAGE GROSS 456.00 Under Deck 427.00 NET 425.00 Built at Renfrew By whom Lobnitz & Co., Ltd. Owners' Address Manchester Ship Canal Co. Owners' Address (if not already recorded in Appendix to Register Book) Port belonging to Manchester

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

WB=CellDBorDBa total capacity tons. FPT tons; uE&B feet; APT tons; MT feet tons. N.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 89863 Port Lw. CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. * A1, Hopper Barge, 9.24. D.B.S. 9.24. * DB. - 7.20. SS. Lw No. 1-24.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Feet). When put on, Month Year
Decks	State if Tanks now tested	Engine Room Skylights	Boats
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Coamings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Outside Plating	Rudder	Hatches	Equipment letter
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Transoms	Windlass	Caulking ditto	Cables (State if now ranged)
Frames	Have Pumps now been examined and found efficient?	Treemails ditto	„ length (on board) size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stems ditto	„ Rule length size
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Floors		Ditto ditto at other places ditto	
Keelsons		Stringers, Clamps & Shelves ditto	
Stringers		Salting (State if examined.)	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

	Fees applied for,	Received by me,
Survey Fee (per Section 29)	19	19
Special Damage or Repair Fee (if any) (per sec. 29)		
Travelling Expenses (if chargeable)		
Second Surveyor's Fee (if any)		

Committee's Minute Character Assigned with draw class to insert... FRI. 1 OCT 1926 Decision of Classing Comm. Confirmed... Surveyor to Lloyd's Register of Shipping. General Committee Thursday 4th October 1926. Lloyds Register Foundation