

1m.9.23.

1

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *St. S.S. "SUNFIELD"*

Rpt. *div. No. 85971*  
*Off. No. 144466*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

*Subject Permanent repairs to be effected in way of the hawse pipes at the Owners convenience.*

Damage through *heavy weather*

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed .....									
Removed and faired or repaired.....									
Faired or repaired in place.....									

Other items:- *Vessel placed in dry dock + bottom recoated  
Bedwarks repaired + stringer plating + gunwhale  
bar faired. New main lower mast fitted.*

It is submitted the vessel is worthy to remain as classed with  
record of Survey 10, 23 *Off.* as recommended, subject as above

*100 A.1. } subject etc.  
10, 23 Off.*

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book.



Lloyd's Register  
Foundation

009827-009838-0096

*T.P.*  
*30.10.23*