

Vessel placed in dry dock bottom & middle chined plating & c

BRITISH CORPORATION.

25 AUG 1949

by Chief Ship Surveyor

Received from Chief Ship Surveyor

GB
SEL'S NAME "HELEN SEABRIGHT" REPORT Lon. No. 118545

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel is classed BS* (With freeboard).

The LONDON Surveyors report, the vessel placed in dry dock and minor repairs effected to shell plating, etc. (p & s).

The upper portion of the rudder main piece which was found twisted has been renewed with tested material.

IT IS SUBMITTED the vessel is eligible to remain as classed by the British Corporation, with record of docking 7.49. *and notation of Annual Survey 7.49.*

BS* (With freeboard)
7.49 Yar.

~~IT IS FURTHER SUBMITTED the GLASGOW (Blywood Square) Office be requested to furnish particulars of the chain cable equipment for this ship, in order that the results of the ranging of the equipment may be checked.~~



Lloyd's Register
Foundation

*BM.
18.8.49.*

009839-009847-0108