

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey

74196 on the Wood, Iron or Steel Tonnage Built at Glasgow By whom D. W. Henderson & Co. Ltd. When 1929 8

TONNAGE - 970 Owners South Indian Ry. Co. Ltd. Owners' Address Port belonging to Glasgow

UNDER DK 801 Managers

NET 377

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

B=CellDBorDBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

tal capacity tons. FPT tons; APT tons; MT feet tons.

ast Report, No. 637 Port Cto.

For Service between Rameswaram & Tale Manaan.

Fitted for oil fuel 8.29 F.P. above 150°F.

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE			
.....	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
.....	State if Tanks now tested	Engine Room Skylights.....	(State if on Felt),
.....	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month.....
.....	Ceiling.....	Scuppers	Boats
.....	Cement or Asphalt	Cargo Hatchways	Masts, Yards, &c.
.....	(State which.)	Hatches	Condition, how ascertained
.....	Rudder	Planking of Wood Vessels.....	(State if wedges removed)
.....	Steering gear and its connections	Caulking ditto.....	Sails.....
.....	Windlass.....	Treenails ditto.....	Equipment letter
.....	Have Pumps now been examined and found effi-	Breasthooks & Stemson ditto.....	Anchors, No. of
.....	cient?	Transoms, Pointers, & Crutches ditto.....	Cables (State if now ranged).....
.....	Have Sluice Valves now been examined and found	Timbers of Frame at openings ditto.....	„ length..... size.....
.....	efficient?	Ditto ditto at other places ditto.....	(on board)
.....	Have Watertight Doors now been examined and found	Stringers, Clamps & Shelves ditto.....	„ Rule length..... size.....
.....	efficient?	Salting ditto.....	Hawser & Warps
.....	Have Ventilators and their Coamings been examined	(State if examined.)	Standing and Running Rigging.....
.....	and found efficient?		

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute WED. 8 APR 1930

Character Assigned insert

Wife Own Lo 9.4.31

Cto (S)

010079-010088-0011

Surveyor to Lloyd's Register of Shipping General Committee Thursday, 9th April 1930