

attributed solely to neglect, but consider the Engine Room staff to be
undermanned for a long journey under tropical conditions.

HSM

N.B.—If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

Noted that
this report is eligible to
remain as CLASSIFIED.

17/1/74



© 2021

Lloyd's Register
Foundation