

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 98822

17 JUN 1931

(Received at London Office)

Date of writing Report _____ When handed in at Local Office 15 JUNE 1931 Port of LIVERPOOL

No. in Reg. Book. 81175 Survey held at Birkenhead Date, First Survey 7 Last Survey 11th June 1931
 on the Machinery of the Wood, Iron or Steel Twin Sc. "PERCH ROCK" (No. of Visits 1)

Tonnage { Gross 766 Vessel built at Dundee By whom Caledon S. B. & Co. Ltd. When 1929-4.
 Net 285 Engines made at Dundee By whom Caledon S. B. & Co. Ltd. When 1929

Nominal Horse Power 183 Boilers, when made (Main) 1929 (Donkey)

No. of Main Boilers 258 Owners The Mayor, Alderman & Burgesses of the Borough of Wallasey Managers Group of Wallasey
 Owners' Address (if not already recorded in Appendix to Register Book.)
 Port Liverpool Voyage _____

No. of Donkey Boilers 180 Surveyed Afloat or in Dry Dock West Hoat
 (State name of Dock.)

No. of Donkey Boilers in Main Boilers 180 in Donkey Boilers

Last Report No. _____ Port _____

Particulars of Examination and Repairs (if any) Drinking

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey "

Why was this not done, state for what reasons? Boilers not due for survey.

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has the screw shaft now been drawn and examined? No Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now been changed? If so, state reasons _____

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Not taken - gland not removed.

If any Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

The Vessel placed in drydock, propellers and outside fastenings examined and found in good order. Wear down not taken - gland not removed.

General Observations, Opinion, and Recommendation:— The machinery of this vessel as stated clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)
seen is eligible in my opinion to remain as classed without fresh record of survey.

Fee (per Section 29).....	£ : :	Fees applied for
Damage or Repair Fee (if any).....	£ : :	
Expenses (if chargeable).....	£ : :	Received by me,

H.R. Howells
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute _____
 signed As now ger

LIVERPOOL 16 JUNE 1931



Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to _____

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Y
Rm
17.6.31

[Faint handwritten notes and bleed-through from the reverse side of the page, including dates and names.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation