

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "NORDELITE"

REPORT

Hul	59337
Mch	15244
Lon	No. 125418

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 2SCSA

6 cylinder 10 $\frac{1}{2}$ " - 13 $\frac{1}{2}$ "

New MN 90

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner No

If fitted with an outside gland of approved type Yes

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 21.2.52. for a service speed of 310 RPM, provided a notice board be fitted at the control station stating that the engine is not to be operated continuously below 100 RPM and the tachometer be marked accordingly. The machinery certificate should be endorsed accordingly and a suitable entry made in SRL.

LH

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \*LMC 5,53

adun

22.7.53.



© 2021

Lloyd's Register  
Foundation



011057-011061-0328