

011595-011602-0160

30 MAR 1953 4E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "MONT SANDRA" REPORT Nwc. No. 110283.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

MBS due 6.53 partly held 9.52 now reheld.

Blr.S. due 9.52 partly held 12.52 now completed and screwshaft examined.

Docking. An emergency fire pump sea suction valve fitted at aft end of shaft tunnel.

Machinery and boilers reconditioned. A new tested secondary feed heater fitted, some bearings remetalled. Main steam pipes tested.

IT IS SUBMITTED that this vessel is eligible to remain as classed, with fresh record MBS 2.53

Blr.S. 12.52

S. 2.53

MSP 2.53.

30.3.53.

© 2021

Lloyd's Register
Foundation