

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office.....)

Date of writing Report _____ 19 _____ When handed in at Local Office _____ 19 _____ Port of Reykjavik

No. in Reg. Book. 07600 Survey held at Depehjudis & Reykjavik Date. First Survey 20 August Last Survey 8 December 1946
 on the Machinery of the Wood, Iron or Steel W. Faxi (No. of Visits 62)

Tonnage { Gross 321 Vessel built at Selby By whom Cocaine & Sons L.D. Year. Month. 1917-7
 Net 175 Engines made at Halifax By whom Campbell Bros & Co. L.D. When 1917
 Nominal Horse Power 87 Boilers, when made (Main) 1917 (Donkey)
 No. of Main Boilers 1 Owners Taxa Klettur H/F. Owners' Address _____
 No. of Donkey Boilers 0 Managers _____ (if not already recorded in Appendix to Register Book)
 Steam Pressure in Main Boilers 200 lb. Port _____ Voyage _____
 in Donkey Boilers _____

Last Report No. _____ Port _____
 Particulars of Examination and Repairs (if any) _____

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? _____

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

" " Donkey " " " " _____

If this was not done, state for what reasons _____

And what parts of the Boilers could not be thus thoroughly examined? none

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? _____

State latest date of internal examination of each boiler 2 December 1946 Present condition of funnel(s) good

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes. To what pressure were they afterwards adjusted under steam? 200 lb.

Did the Surveyor examine the Safety Valves of Donkey Boiler? _____ To what pressure were they afterwards adjusted under steam? _____

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes. _____, and of the Donkey Boilers? _____

Did the Surveyor examine the drain plugs of the Main Boilers? Yes _____, and of the Donkey Boilers? _____

Did the Surveyor examine all the mountings of the Main Boilers? Yes _____, and of the Donkey Boilers? _____

Has the screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no.

Has shaft now been changed? _____ If so, state reasons _____

Has the shaft now fitted been previously used? _____ Has it a continuous liner? _____ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? _____

State date of examination of Screw Shaft 3 Decemb. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 0.5 mm.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes all parts examined and fully renewed

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes, megger tested.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Caught Special Survey.

All cylinders, pistons, slide valves, pumps, condenser, shafting, propeller, sea connecting and their fastenings and the general arrangement of valves, cocks, pipes, fittings, suction, roses etc. carefully examined and found to be in good condition.

The boiler with its slide valves, doors, mountings, superheater and etc. carefully examined inside and outside, and the safety valves afterwards adjusted under steam to the working pressure stated above.

The tailshaft was drawn and carefully examined on flange, shaft line, cone, thread, key groove, key and nut, and found to be in good condition, the propeller examined and found in good condition. The stern tube was carefully examined on tube, brass lining, necking and gland and all found to be in good condition. P.T.O.

General Observations, Opinion, and Recommendation:— This vessel's machinery is in good condition, in my opinion, although to remain as closed and to have the record of LMC 11,46. C.L. 11,46 in Register Book.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, L.M.C. 9,11, or CS 3,34, 110 lb., F.D., &c.)

Survey Fee (per Section 20) £25: 4: 0 Fees applied for 18/12 1946

Special Damage or Repair Fee (if any) (per Section 20.) £21: 0: 0

Traveling expenses (if chargeable) £: : : Received by me, 18/12 1946

Committee's Minute _____

Assigned + LMC 12,46

5 12,46

CHARACTER (for Special Survey Date of last Survey and of Periodical Surveys.)	Years assumed expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A 1		+ L M e.
Stm Trawl 1944		M.S. 2,43
S.S. Reg. No. 3-11,33		B.S. 1/45, 44
S.S. Reg. No. 2-42.		C.L.S. 43.

If a survey has been held on ship, or when will it be sent? If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book. Is a Certificate required? If so, to be sent to _____



All following repairs were carried out on the machinery:
The HP piston and valve rods were dressed up and fitted with new metallic packings.
The MP piston rod dressed up and fitted with new metallic packing.
The NIP crosshead dressed up on journals and the brasses fitted with new lath.
The trustaft was brought on yard and dressed up on callers.
The heavy-shoe elements for trustbearing were all fitted with new lath.
The tailaft brought on yard and dressed up on line.
The stern tube brass drawn, fitted with new lignum vitae and bored up to fit the shaft.
The deck engine brought on yard and overhauled.
The electric lighting engine overhauled, cylinders and valve liners bored up and piston and valve renewed. The dynamo brought on yard and fixed up.
The whole system of switch boards with all equipment, conduits, lamps and etc. throughout the vessel was overhauled, afterwards magnets tested and found in order.
The sea connections were removed from ship sides, repaired and tested, and afterwards refitted on ship sides with new studs, nuts and strainers.
The main steam line and superheater were tested by an hydraulic pressure of 400 $\frac{3}{4}$ lb and found in good condition.
The boiler mountings were repaired.
The boiler lagging was removed, the boiler carefully examined and the lagging renewed.
In addition to these repairs, stated above, a great lot of small and trivial repairs were carried out on the machinery.

W. Chapman.



© 2021

Lloyd's Register
Foundation