

## REPORT ON STEAM RECIPROCATING ENGINE MACHINERY.

Date of writing Report 19 10 1941 When handed in at Local Office 5 MAY 1941 Port of HULL  
 No. in Survey held at Hull Date, First Survey 25. 10. 40. Last Survey 30. 4. 1941.  
 Reg. Book. on the H.M.T. "ARRAN" (Number of Visits 46)  
 Built at Beverley By whom built Coak, Wotton & Gemmell Ltd Yard No. 671 When built 1941-5  
 Engines made at Hull By whom made Chas. D. Holmes & Co Engine No. 1584 When made 1941-5  
 Boilers made at Hull By whom made Chas. D. Holmes & Co Boiler No. 1584 When made 1941-5  
 Registered Horse Power 156 Owners The Admiralty Port belonging to ✓  
 Nom. Horse Power as per Rule 156 Is Refrigerating Machinery fitted for cargo purposes no Is Electric Light fitted Yes  
 Trade for which Vessel is intended ✓

ENGINES, &c.—Description of Engines Triple expansion Revs. per minute 160  
 Dia. of Cylinders 13 1/2 - 23 - 38 Length of Stroke 27 No. of Cylinders 3 No. of Cranks 3  
 Crank shaft, dia. of journals 7 1/2 as per Rule 7 1/2 Crank pin dia. 7 1/8 Crank webs Mid. length breadth Thickness parallel to axis 4 13/16  
 as fitted 7 1/8 Mid. length thickness shrunk Thickness around eye-hole 3 15/16  
 Intermediate Shafts, diameter as per Rule 7 1/2 Thrust shaft, diameter at collars as per Rule 7 1/2  
 as fitted 7 1/4 8.2 8.10 as fitted 7 1/8  
 Tube Shafts, diameter as per Rule 1 Screw Shaft, diameter as per Rule 8 1/4 Is the tube shaft fitted with a continuous liner no  
 as fitted 1 as fitted 8 1/4  
 Bronze Liners, thickness in way of bushes as per Rule 1 Thickness between bushes as per Rule 1 Is the after end of the liner made watertight in the propeller boss ✓  
 as fitted 1 as fitted 1  
 If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner ✓  
 If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive ✓  
 If two liners are fitted, is the shaft lapped or protected between the liners ✓ Is an approved Oil Gland or other appliance fitted at the after end of the tube at ✓ Length of Bearing in Stern Bush next to and supporting propeller 36 1/2  
 a t ✓ If so, state type Newark whether Moveable no Total Developed Surface 30 sq. feet  
 Propeller, dia. 105 Pitch 9'-4" No. of Blades 3 Material B.S. Can one be overhauled while the other is at work Yes  
 Feed Pumps worked from the Main Engines, No. 2 Diameter 2 1/2 Stroke 15 Can one be overhauled while the other is at work Yes  
 Bilge Pumps worked from the Main Engines, No. 2 Diameter 2 1/2 Stroke 15 Can one be overhauled while the other is at work Yes  
 Feed Pumps { No. and size One - 4 x 6 x 12 Weirs Pumps connected to the { No. and size One - 6 x 5 1/2 x 15 Weirs } also  
 How driven Independent steam Main Bilge Line How driven Independent steam down on  
 Ballast Pumps, No. and size none Lubricating Oil Pumps, including Spare Pump, No. and size none  
 Are two independent means arranged for circulating water through the Oil Cooler none Suctions connected to both Main Bilge Pumps and Auxiliary Bilge Pumps;—In Engine and Boiler Room Engine room 2 @ 2' dia + one @ 3 1/2' dia. Holdolds 2 @ 2' dia.  
 In Pump Room none In Holds, &c. One @ 2' dia in each of the following - forepeak, chain locker, ASD's space, magazine, spirit room, Bunker, shaft space, aft peak.  
 Main Water Circulating Pump Direct Bilge Suctions, No. and size One - 5" Independent Power Pump Direct Suctions to the Engine Room Bilges, No. and size One @ 3 1/2" including above  
 Are all the Bilge Suction Pipes in holds and tunnel well fitted with strum-boxes Yes  
 Are the Bilge Suctions in the Machinery Space led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges Yes  
 Are all Sea Connections fitted direct on the skin of the ship Yes Are they fitted with Valves or Cocks Yes  
 Are they sized sufficiently high on the ship's side to be seen without lifting the stakehold plates Yes Are the Overboard Discharges above or below the deep water line at W.L.  
 Are they each fitted with a Discharge Valve always accessible on the plating of the vessel Yes Are the Blow Off Cocks fitted with a spigot and brass covering plate no  
 What Pipes pass through the bunkers Dead tank suction How are they protected wood casing  
 What pipes pass through the deep tanks none Have they been tested as per Rule Yes  
 Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times Yes  
 Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one compartment to another Yes Is the Shaft space watertight Yes Is it fitted with a watertight door no Access from flat above

MAIN BOILERS, &c.—(Letter for record 5 Total Heating Surface of Boilers 2650 sq  
 Which Boilers are fitted with Forced Draft all Which Boilers are fitted with Superheaters none  
 No. and Description of Boilers One S.B. Working Pressure 200 lbs sq  
 IS A REPORT ON MAIN BOILERS NOW FORWARDED? Yes  
 IS A DONKEY BOILER FITTED? no If so, is a report now forwarded? ✓

Can the donkey boiler be used for domestic purposes only ✓  
 PLANS. Are approved plans forwarded herewith for Shafting 7.7.39 Main Boilers 7.7.39 Auxiliary Boilers none Donkey Boilers none  
 (If not state date of approval)  
 Superheaters none General Pumping Arrangements none Oil fuel Burning Piping Arrangements none

## SPARE GEAR.

Has the spare gear required by the Rules been supplied Yes See attached list.  
 State the principal additional spare gear supplied

The foregoing is a correct description.  
 FOR CHARLES D. HOLMES & CO., LTD.

Manufacturer.



© 2021

Lloyd's Register  
Foundation

014738-014750-0253



1940.		1941.	
Dates of Survey while building	During progress of work in shops - -	Oct. <sup>24 28.</sup> 25, 31. Nov. 8, 11, 14, 15, 23, 28. Dec. 6, 16, 17, 27, 30. Jan. 1, 2, 3, 8, 10, 13, 15, 18, 22, 25, 28, 30. Feb. 1, 9, 24. Mar. 7, 13, 14, 22, 26, 28. Apr. 2, 7, 10, 11, 19, 21, 24, 25, 28, 29, 30.	
	During erection on board vessel - - -		
	Total No. of visits	46.	

Dates of Examination of principal parts—Cylinders		Slides		Covers	
Pistons	28-11-40	Piston Rods	8-1-41	Connecting rods	8-1-41
Crank shaft	27-12-40	Thrust shaft	23-11-40	Intermediate shafts	6-12-40
Tube shaft	✓	Screw shaft	24-10-40	Propeller	8-11-40
Stern tube	28-10-40	Engine and boiler seatings	25-10-40	Engines holding down bolts	22-3-41
Completion of fitting sea connections	25-10-40	Completion of pumping arrangements	21-4-41	Boilers fixed	22-3-41
Main boiler safety valves adjusted	11-4-41	Engines tried under steam	24-4-41	Engines tried under steam	24-4-41
Crank shaft material	M.S.	Thickenss of adjusting washers	Bore 3/8"	Thickenss of adjusting washers	Bore 3/8"
Intermediate shafts, material	M.S.	Identification Mark	3944 A.E.G. 15-10-40	Identification Mark	3944 A.E.G. 15-10-40
Screw shaft, material	M.S.	Identification Mark	470 E.H. 10-10-40	Identification Mark	470 E.H. 10-10-40
Is an installation fitted for burning oil fuel	no	Is the flash point of the oil to be used over 150°F.	✓	Is the flash point of the oil to be used over 150°F.	✓

Is an installation fitted for burning oil fuel no Is the flash point of the oil to be used over 150°F. ✓  
Have the requirements of the Rules for the use of oil as fuel been complied with ✓  
Is the vessel (not being an oil tanker) fitted for carrying oil as cargo no If so, have the requirements of the Rules been complied with ✓  
If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with ✓  
Is this machinery duplicate of a previous case Yes If so, state name of vessel H.M.T. "BIRCH" Hull up 50672  
**General Remarks** (State quality of workmanship, opinions as to class, &c.)

The machinery of this vessel has been constructed and fitted on board in accordance with the approved Admiralty plans, the specification and the Society's Rules. The workmanship and materials are good and when tried at as near full power as practicable in the River Humber it was found satisfactory in every respect.

The vessel is eligible, in our opinion, when classed to have the records of + LMC. 5-41. and D. G. and the notations T. 3 cy. 13½, 23 v 38 156 N.H.P. 200 lb 1. 5B. 3 cy. G.S. 63. H.S. 2650 F.D.

The amount of Entry Fee	...	£	:	:	When applied for,
Special	...	£	75	0	15 MAY 1941
Donkey Boiler Fee	...	£	:	:	When received,
Travelling Expenses (if any)	£	:	:	:	31.5. 41

*Assigned*

+ LMC 4.41

FD



© 2021  
Lloyd's Register  
Foundation