

# Report of Survey for Repairs, &c., of Engines and Boilers.

No. *10454* Date of Writing Report *18<sup>th</sup> June 1891* Port of *Glasgow* (Received at London Office *SAT. 20 JUN 1891*)  
No. in Reg. Book *652* Survey held at *Glasgow* Date, first Survey *11<sup>th</sup> June* Last Survey *17<sup>th</sup> June 1891*  
on the Machinery of the *S. S. "Glan Forbes"* Master *Whyle* No. of Visits *3*  
Tonnage { Gross *2441* Vessel built at *Glasgow* By whom *A. Stephen & Co.* When *1882* . *8*  
Net *1591* Engines made at *Glasgow* When *82* Boilers, when made (Main) *82* (Donkey) *82*  
Registered Horse Power *300* Owners *Cayzer, Irvine & Co.* Port *Glasgow* Voyage *Bombay*  
No. of Main Boilers *2* If Surveyed Afloat or in Dry Dock *Medowide* Class of Vessel & Machinery *SS no 1*  
Steam Pressure in Main Boilers *85* (State name of Dock.) (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) *82.*  
in Donkey Boiler  
Last Survey No. Port

Particulars of Examination and Repairs (if any) *Locking* *+ L.M.C. 8.89*  
(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

*In order to complete boiler survey  
safety valves have been floated -  
New spring has been fitted in the donkey -  
boiler safety valves -*

*The vessel has been placed in dry dock  
when all sea connections were examined  
externally and along with the propeller  
fastenings found in good order. -*

General Observations, Opinion, and Recommendation:— *The above completes*

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1.89, B.&M.S. 1.89, or L.M.C. 1.89, as the case may be.)

*Conditions for recommendations made in  
Glasgow Report No 10131. viz: + L.M.C. 9.90.*

Office or Registration Fee (per Sec. 27)	£	:	Fees applied for
Survey Fee (per Section 28)	£	:	18
Special Damage Fee (per Section 28)	£	:	Received by me,
Travelling Expenses (if chargeable)	£	:	18

\*State if Certificate is required.

Committee's Minute *TUES. 23 JUN 1891*

*TUES. 23 FEB 1892*

Assigned *+ L.M.C. 9/90*

*John Sanderson*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*Glasgow.*  
Lloyd's Register  
Foundation  
GLS162-0221

167579a  
It is submitted that this.

vessel is eligible to have

+ 2 N.C. 19-90 recorded

Handwritten text on lined paper, possibly a signature or initials.

Handwritten text, likely bleed-through from the reverse side of the page, including the word "MAY" and some illegible cursive script.

15.9.22

18

1850

22

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page is bound, showing the stitching and the inner cover material. There is no text or other markings on the page.

入

101

10

[illegible]

99

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding of the book, with visible stitching or staples. There is no text or other markings on the page.

2/3



1990

414

20  
vd19  
's

Re

ste

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

REQUESTED NOT TO WRITE ACROSS THIS MARGIN.