

Report of Survey for Repairs, &c., of Engines and Boilers.

No. *11241* Date of Writing Report *16th Jan 1892* Port of *Glasgow*
No. in *685* Survey held at *Glasgow* Date, first Survey *and* Last Survey *13th Jan 1892*
g. Book. on the Machinery of the *S.S. Glen Monroe* Master *Alexander* No. of Visits *One*
Gross *2197* Vessel built at *Sunderland* By whom *Bartram, Haswell & Co.* When *1881. 11*
Net *1437* Engines made at *Newcastle* When *81* Boilers, when made (Main) *81* (Donkey)
Registered Horse Power *300* Owners *Cayzer, Irvine & Co* Port *Glasgow* Voyage *East*
No. of Main Boilers *2* If Surveyed *Afloat or in Dry Dock* *Meadowside*
Steam Pressure in Main Boilers *90 lbs* (State name of Dock.)
in Donkey Boiler *—* Class of Vessel & Machinery *+100A 1*
Last Survey No. *—* Port *—* (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) *S.S.N. 1. 87.*

Particulars of Examination and Repairs (if any) *Locking + L.M.C. 12.89. B.S. 3.91.*

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

This vessel has been placed in the above named dock at which time the sea connections were examined externally and along with propeller & fastenings found in good order. — The machinery of this vessel will be converted to triple expansion on the return from present voyage. —

General Observations, Opinion, and Recommendation: — *As far as seen the*

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1.89, B.E.M.S. 1.89, or L.M.C. 1.89, as the case may be.)

machinery of this vessel appears to be in good order and is in my opinion eligible to remain as classed without any fresh record of survey. —

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	16
Special Damage Fee (per Section 28)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	Received by me,
				18

* State if Certificate is required

Committee's Minute *TUES. 26 JAN 1892* *FRI 30 SEP 1892*

Assigned *Deferred* *Glasgow.*

Lloyd's Register Foundation GLS164-0072

1124198

It is submitted that
this vessel is eligible for
remain in service.

N.A.

25-1-92

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE STATIONERS ARE REQUESTED TO WRITE ACROSS THE MARGIN



© 2019
Lloyd's Register
Foundation