

119549

If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Dec. 27 12.92
 Defect of leakage
 the back furnace door
 has been cut out
 and patched
 O.H.S.
 27 12.92



© 2019
 Lloyd's Register
 Foundation

THE SURVEYOR'S REPORT IS NOT TO BE WRITTEN ACROSS THE PAGE BUT IN THE MARGINS. IT IS ALSO NOT TO BE WRITTEN ON THE REVERSE.