

No. 13296

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

13 NOV 1894

Date of writing Report 18 When handed in at Local Office 18 Port of Glasgow
No. in Reg. Book. 713 Survey held at Glasgow Date, First Survey S. S. City of Vienna Last Survey 15 Nov 1894
on the Machinery of the Wood, Iron or Steel Master Anderson
Tonnage { Gross 4672 Vessel built at Belfast By whom Clark & Co When 1890 6
Net 3228 Engines made at Glasgow When 1890 Boilers, when made (Main) 1890 (Donkey)
Registered Horse Power 700 Owners G. Smith & Son Port Glasgow Voyage India
No. of Main Boilers 160 If Surveyed Afloat or in Dry Dock Queens Dock
Steam Pressure in Main Boilers 160 (State name of Dock.)
in Donkey Boilers 80

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100A1</u> <u>9.93</u>		<u>+LMC</u> <u>8.94.</u>

Last Survey No. 15 Nov 1894 Port Glasgow
Particulars of Examination and Repairs (if any) Limit on Thrust.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Not due

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Examined the Thrust shaft and found a groove about 2 inches deep & 1 1/2" long and between two of the Thrust collars. This is the point where the flaw had been detected, but there is no sign of a flaw or crack at the bottom of this groove and in my opinion the shaft is in a safe working condition.

The Thrust shaft is 16" diameter between the rings, according to the scales it need not have been made larger than 14 1/8".

General Observations, Opinion, and Recommendation:— As far as seen the
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4, 91, B.M.S. 4, 91 or L.M.C. 4, 91, 140 lb., F.D., &c.)
Machinery of this vessel is in a safe working condition and
eligible in my opinion to remain as classed and to have her
name removed from the limited list

Office or Registration Fee (per Sec. 27) £ : : Fees applied for
Survey Fee (per Section 28) £ : : 18
Special Damage Fee (per Section 28) £ : :
Travelling Expenses (if chargeable) £ : : Received by me, 18

State if Certificate is required

Committee's Minute

Assigned

As now
but without limit

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI 1 MAR 1895

FRI 21 JUN 1895

GLS 171-0021

Lloyd's Register
Foundation

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

13296 glo

It is submitted that
this vessel is eligible to
remain AS CLASSED, and

to have its name removed
from the limited list
for the thrust shaft

W.A. 1894
14-11-94



© 2019

Lloyd's Register
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.