

# ANNUAL SURVEYS.

7011  
11/11

No. 507 Survey held at London Date Dec 1st 1840  
 on the Bk Helena Master W Leslie  
 Tonnage 327 Built at Danish Bidge When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners Hervenson jr  
 Port belonging to Danish Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock London Dock

London 272, 2409 & Original Survey, No. 3338 Port of London March 1841 Classed F. 1

The Surveyor is required to state the present Condition of the

Decks <u>fair condition</u>	Breasthooks <u>Sound</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>Moderate</u>	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame <u>fair above sea</u>	Masts, Yards, Sc. _____
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Well found</u>
Plank Shears _____	Wales <u>fair condition</u>	Cables _____
Waterways _____	Plank and Treennails <u>"</u> (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings _____	Rudder <u>good</u>	Standing & Running Rigging <u>good</u>
	Windlass _____	Copper <u>as 1837 to Light work</u>

General Observations and Opinion, Some of the Beams & Braces are defective & overboard the  
 as required by the Instructions, Beams on 2, and from their general appearance I am of opinion  
is only fit for the conveyance of cargoes not in their  
nature subject to sea damage and should remain as

Committee Minute 14th Dec 1841  
 Character assigned F. 1

No. 136 Survey held at London Date Dec 1st 1840  
 on the By Victory Master J Frost  
 Tonnage 201 Built at Underland When built 1830  
 By whom built \_\_\_\_\_ Owners Starbuck, W. Shipping Co  
 Port belonging to Starbuck Destined Voyage to Constantinople  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 913, Port of Underland, London 6950, 1830 Classed F. A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, Sc. _____
Spirketting <u>good</u>	Topsides _____	Sails <u>good</u>
Plank Shears _____	Wales <u>good</u>	Cables _____
Waterways _____	Plank and Treennails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>sufficient</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>YM 30</u>

General Observations and Opinion, In 1839 sheathed with yellow metal both the sides & bottom  
 as required by the Instructions, at the present in good condition & continues safe

Committee Minute 11th Dec 1840  
 Character assigned F. 1

© 2010  
 Lloyd's Register  
 Foundation