

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUES. 10 MAY 1892

No. 113	Date of Writing Report. 9.5.92	Port of London
No. in Reg. Book. 113	Survey held at London on the Machinery of the S.S. Mallard	Date, first Survey Mar. 24 Test Survey Mar. 26 1892.
Tonnage 1250	Vessel built at Dundee	Master
Net 803	By whom Gourlay Bros.	When 1882-5
Registered Horse Power 140	Engines made at do	Where 1882 Boilers, when made (Main) 1882 (Donkey)
No. of Main Boilers 2	Owners G. S. H. Co.	Port London Voyage
Steam Pressure in Main Boilers 75 lbs	If Surveyed Afloat or in Dry Dock Paris	Class of Vessel & Machinery - 100 A 1.5.0 (As in Register Book, including date of - I.Y.C.C. 12.90 Special Survey of ship and Boiler Survey)
in Donkey Boiler 50	(State name of dock.)	S.S. Lon. No 2-90
Last Survey No. 2686 by Port 1100		

Particulars of Examination and Repairs (if any) Annual B.S.

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this matter.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination of same?

Do. " Donkey " "

If this was not done, state for what reason?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of these parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valve of Donkey Boiler?

To what pressure were they afterwards adjusted?

Main boilers exd. internally & externally & found in good condn.
Safety Valves exd. in good condn. & tested under stm. to W.P.
of 75 lbs.

Winch boiler exd. found in good condn. & Safety valve
tested under stm. to 50 lbs.

To complete B.S. the Winch boiler Safety Valve has to be exd.

General Observations, Opinion, and Recommendation:—

(State clearly what alterations, if any, is suggested to be made in the existing classification and notations of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 1.5.0, H.D.S. 1.5.0 or G.O.B.C. 1.5.0, as the case may be.)

The boilers being now in good & safe working condn. renders the vessel eligible on my opinion to remain as classed than the next after B.S. & a fresh date recorded when the Winch boiler safety valves have been exd.

Office or Registration Fee (per Sec. 27) £ 2 - - -

Fee applicable	10/5/1892
Received by	2/15/1892

Survey Fee (per Section 28) £ 2 - - -

Special Damage Fee (per Section 28) £ 2 - - -

Travelling Expenses (if charged) £ 2 - - -

Geo. E. Wilkinson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required.

Committee's Minute FRI 13 MAY 1892

TUES. 16 AUG 1892

Assigned

Deferred
for Compt.



© 2019

Lloyd's Register
Foundation

LON696-0126

It is submitted that this
vessel WILL BE eligible for
the record B.S. 3-92 when the safety
valves of the donkey boiler have
been examined.

W.A.
10-5-92

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation