

Report of Survey for Repairs, &c., of Engines and Boilers.

FRI 18 AUG 1893

(Received at London Office)

Date of writing Report *Aug 17 1893* When handed in at Local Office *is* Port of *London*
 No. in Reg. Book. *141* Survey held at *London* Date, First Survey *and* Last Survey *Aug 16 1893*
 on the Machinery of the *Wood, Iron or Steel* *SS. HAWARDEN CASTLE* Master *Webster*
 Tonnage { Gross *4380* Vessel built at *Glasgow* By whom *J. Elder & Co.* When *1883* 1.
 { Net *2556* Engines made at *Do.* When *1891* Boilers, when made (Main) *1891* (Donkey) *1891*
 Registered Horse Power *860* Owners *J. Lawrie & Co.* Port *London* Voyage *S. Africa*
 No. of Main Boilers *two* If Surveyed *At or in Dry Dock* *Green Dry Dock*
 Steam Pressure in Main Boilers *160 lbs* (State name of Dock.) *Poplar*
 in Donkey Boiler *✓*

Last Survey No. *Port*
 Particulars of Examination and Repairs (if any) *Condition.*

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Examined propeller, Norn bush & sea connections fastenings, all found to be in good condition.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Yearly Annual Survey, Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
<i>100. A. 1. 5. 93.</i>	<i>LM.C. 7. 91.</i>	<i>N.B. 7. 91.</i>
<i>SS. CLS. No. 3. 7. 91.</i>		

No. No. Survey not due

No

No

Completed.

General Observations, Opinion, and Recommendation:— *This vessel's machinery is now as far as seen in good condition. & in my opinion the vessel is eligible to remain as classed without fresh record of survey.*

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	Received by me,
Travelling Expenses (if chargeable).....	£	:	:	18

*State if Certificate is required


Committee's Minute

TUE 22 AUG 1893

Assigned

As now

P. M. Salmon.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register Foundation

LON699-0431

State if a Report is also now sent on the Ship

*Certificate to be sent to

*LAPH—Form No. 9—Transfer Ink—10,000, 20/7/83.

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

21/8/93 -

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

21/8/93

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

© 2019
Floyd's Register
Foundation