

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

MON 11 OCT 1897

Date of writing Report

When handed in at Local Office

11 Oct 1897

Port of London

No. in Reg. Book.

Survey held at

Date, First Survey

Last Survey

1897

126

on the Machinery of the Wood, Iron or Steel

S. I. Mallard

Master

Hayes

Tonnage

Gross 1250
Net 803

Vessel built at Dundee

By whom

Gourlay Bros & Co

When 1882

Registered Horse Power

130

Engines made at

When

Boilers, when made (Main)

Donkey

No. of Main Boilers

2

Owners Genl Steam Navigation Co

Port London

Voyage Mediterranean

No. of Donkey Boilers

1

Steam Pressure

in Main Boilers 70 lbs

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
For Special Survey.
Date of last Survey and of Periodical Surveys.

Years Assigned now or expired.

Machinery and Boiler Surveys (including date of N.B., if any).

Last Survey No.

Port

Particulars of Examination and Repairs (if any)

In Dry Dock. +100 A.I. 2.97

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

S. I. Lou 103.8.95

+100 E. 8.95

O.S. 9.96

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

Donkey

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

What remains to be done?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Wooden: Propeller, Stern-bush and outside fastenings of the Sea connections examined and found in Satisfactory condition.

The Owner's attention has been called to this vessel being now due for Boiler Survey. No arrangements made at present for this survey but it is expected that same will be held shortly.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L.M.C. 9,95, 140 lb., F.D., &c.)

The Machinery of this vessel so far as has been seen is in good order and in my opinion eligible to remain as classed, without fresh record.

	Fees applied for
Office or Registration Fee (per Sec. 27)	£ : : 18
Survey Fee (per Section 28)	£ : : 18
Special Damage Fee (per Section 28)	£ : : 18
Travelling Expenses (if chargeable)	£ : : 18

D. Christie

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

Assigned Deferred

FRI. 15 OCT 1897

TUES. 8 MAR 1893

B. S. due 9.97. will be held shortly

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as CLASSED.

H.S.
11.10.97

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation