

No. 1248 Survey held at Sunderland Date March 1839 1248  
 on the Snow. "Exquisite" Master Marrow  
 Tonnage old 221 Built at Sunderland When built 1839  
 By whom built Taylor & Co Owners Baker  
 Port belonging to Sunderland Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Building

Length aloft.....	Feet. Inches.	Extreme Breadth .....	Feet. Inches.	Depth of Hold .....	Feet. Inches.
Scantlings of Timber.			Thickness of Plank.		
	Inches.	Inches Middle Ends	Outside.	Inches.	Inside.
Timber and Space.....	each 10 1/4		Keel to Bilge .....	3	Foot Waling.....
Floors.....	sided 10 1/4	Moulded 11 1/2 9	Bilge Planks .....	4	Bilge Planks .....
1 <sup>st</sup> Foothooks.....	" 9 10 "	" 0 "	Bilge to Wales .....	3 2/3	Ceiling in Flat .....
2 <sup>nd</sup> Ditto .....	" 8 9 "	" 7 1/2 "	Wales .....	4	Ditto Bilge to Clamp .....
3 <sup>rd</sup> Ditto.....	" 8 "	" 6 1/2 "	Topsides .....	2 1/2	Hold Beam Clamps .....
Top Timbers .....	" 7 "	" 4 1/2 "	Sheer Strakes .....	3	Deck Beam Ditto.....
Deck Beams ... Number of 20 .....	" 8 to 9 "	" 8 to 9 5 "	Plank Sheers .....	3	Ceiling 'twixt Decks .....
Hold Beams .... Dp. do. 10 .....	" 10 "	" 10 "	Water-ways .....	4	Hold Beam Shelves .....
Keel .....	" 10 "	" 8 1/2 "	Upper Deck .....	3	Deck Beam ditto .....
Kelsons .....	" 11 "	" 20 "			
Size of Bolts in Fastenings.					
Copper.	Inches	Copper.	Inches.	Iron.	Inches.
Heel-Knee, and Dead Wood abaft .....	1 1/10	Bolts thro' the Bilge and Foot Waling .....	3/4	Hold Beam .....	7/10
Scarps of Keel.....	N <sup>o</sup> 25 3/4	Butt End Bolts .....	3/8	Deck Beam .....	9/4 9/10
Floor Timber Bolts.....	1	Lower Pintle of the Rudder .....	3		
Kelson ditto.....	1 1/10			same in Iron above the Copper .....	{
Transoms and throats of Hooks .....	1				
Arms of Hooks .....	1 7/10				

**Timbering.**—The Space between the Floor Timbers and Lower Foothooks in this Vessel is 1 to 2 Inches. The Space between the Top-timbers is 3 1/4 to 5 Inches. The Stem, Stern Post, Transoms, Aprons, Knight Heads, Hawse Timbers, are composed of English and Foreign Oak and are generally free from all defects. Her Floors and first Foothooks are composed of English and Foreign Oak Timber. Her other Foothooks and Top Timbers of English and Foreign Oak. Her Shifts of the first and second Foothooks are not less than 3 to 3 1/2 N.B. When reported by you less than the prescribed Rule, then state how many.

The rest of the Shifts of the Frame are generally fair. The Frame is fairly squared from the first Foothook Heads upwards, and actually free from sap, and from thence downwards, the frame is fairly squared.

The alternate Frames are not bolted together every 6 ft.

The Butts of the Timbers are close together; their thickness not less than 1 1/2 to 1 3/4 of the entire moulding at that place.

The Frame is ends chocked with no Butt at each end of the chock.

The Main Kelson is composed of American oak and the False Kelson of American oak.

The Scarps of the Kelsons are not less than 7 feet 6 inches.

The Deck and Hold Beams are composed of American, English and French Oak.

**Planking Outside.**—This Vessel's Plank from the Keel to the first Foothook Heads is composed of French and American Elm.

From the first Foothook Heads to the Light Water Mark of French and American Elm.

From the Light Water Mark to the Wales of Dougic Oak.

The Wales and Black-strokes are of Dougic and English Oak.

The Topsides of English and African Oak.

The Sheer-strokes of English Oak Decks, and state of yellow pine.

The Gunwales of African and English Oak Water-ways of English Oak.

The Shifts of the Planking are not less than 1 1/2 to 2 Feet Inches. N.B. If reported less than the prescribed Rule, state whether

general or partial, and if partial, in what part of the Ship.

The Planking is wrought two and three between.

**Planking Inside.**—The Clamps are composed of Stettin Oak.

the Stringers of Stettin Oak.

The Bilge Planks of Stettin Oak and the remainder of the Ceiling of Stettin and English Oak.

**Fastenings.**—To Hold Beams Iron bands round the bilges stinger on top and 2 iron hanging lines each side.

Deck Beams Double iron hanger lines and stinger below with 2 iron hanging lines each side.

Number of Breasthooks Five one pair Pointers one pair Crutches 2 transom braces each side.

Butts End Bolts are of Iron in the Bottom, and one Bolt in each Butt End through and clenched.

Bilge and Footwaling is bolted through and clenched.

General Quality of Workmanship fair.

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name

Taylor & Co

Surveyor's Name

Jos. S. Lincy

G. F. SEYFANG, PRINTER, FARRINGDON STREET, LONDON.

© 2018



Lloyd's Register  
Foundation

Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

She has SAILS.

N°.		Fathoms.	CABLES, &c.	Inches.	N°.	
2	Fore Sails,	100	Chain .....	10 $\frac{1}{16}$	3	Bower, 10 $\frac{1}{2}$ . 9 $\frac{1}{4}$ . 9 $\frac{1}{2}$
1	Fore Top Sails,	80	Hempen Stream Cable.....	8 $\frac{1}{2}$	1	Stream, 3. 0. 14
2	Fore Topmast Stay Sails,	60	Hawser .....	3 $\frac{1}{4}$	1	Kedge, 1 $\frac{1}{2}$ -
1	Main Sails,	80	Towlines .....	5		All of proper weight.
2	Main Top Sails, and <del>other</del> others	80	Warp .....	4 $\frac{1}{2}$		
			All of <u>good</u> quality.			

ANCHORS.

Her Standing and Running Rigging is well fitted sufficient in size and good in quality.

She has one Long Boat and one Kiff

The present state of the Windlass is good Capstan good and Rudder & Braces good  
with Tyrocks patent  
2 Metal pumps

**General Remarks—Statement and Date of Repairs.**

The Frame is generally of good sound quality, the floors fit well and square. Foothooks are principally of Foreign oak, the remainder all English, it is fairly wrought but indifferent shifted in places, about six scabs of 1 $\frac{1}{2}$  and 2 $\frac{1}{2}$  Foothooks on each side three feet long. Tops are half scarf'd and half battened on 2 $\frac{1}{2}$  has a few on each side wavy & safty. Hawse timbers are a little wavy & safty in the edges.

Plank & outside generally good quality tolerably well wrought and shifted except two butts on Larboana side shot and is fairly clear of sap. Greenails are of Ery oak and app'ly good.

Hull Beams are all Foreign oak the deck beams are mix'd Ery & Foreign, and are app'ly of good quality, the Foreign ones are generally well squared, some of the Ery ones are wavy & safty on the moulding sides, the knees are generally of good quality some of them are wavy & safty, but the upper deck beams are well secured with iron knees and stringers.

Beams, knees & hooks are all sufficiently bolted but indifferently clinched in places. Ceiling is of fair quality, sawn from logs and not well seasoned is generally clear of sap and fairly wrought and shifted.

Commenced building in October 1838 was finished in March 1839

was surveyed as follows  $\frac{22}{1} \frac{6}{2} \frac{19}{2} \frac{15}{3} \frac{26}{3}$

If Sheathed, Doubled, or Felted,

and Date when last done

And I am of opinion this Vessel should be Classed 7 yrs at Pro. D. May

<sup>322</sup> The Amount of the Fee..... £ 3 : 3 : 0 is received by me,

Committee Minute 9 April 1839

Character assigned A 1 pr. 4 years

Ch.