

1

Received from Chief Surveyors

Report S. Fo.

No. 3304.

For the **CHIEF SHIP SURVEYOR**

(1) cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee Report, 24.5.52.

When due

2 Dks (steel) and Webframes.

Longitudinal Framing.

Cell DB UE&B 61' 143t. DTf 35' 948t. APT 122t.

FK. 16 BH (9 to upper dtk. 7 to 2nd dtk) prasp. AYCP. P106', B50', F41'.

Marchy Aft

C.D.
26/8/20

It is concluded the thickness of Port side plating in way of 30" frame spacing has been increased as approved but the Surveyors should be requested to state if this is so.

~~4/25 Mr Carter~~
~~20/9/20~~

MS

9-7-20

© 2020

Lloyd's Register
Foundation

[illegible]