

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 19 When handed in at Local Office 24 19 39 Port of Antwerp
No. in Reg. Book. Survey held at Hoboken Date, First Survey and Last Survey 5-8 19 39
on the Machinery of the Wood, Iron or Steel Tug to M.S. Baudouinville. (No. of Visits One)
Tonnage Gross Vessel built at Hoboken By whom Soc. A. J. Lockenill When 1939-7
Net Engines made at Seranby By whom Soc. A. J. Lockenill When 1939
Nominal Horse Power 1938 Boilers, when made (Main) (Donkey) 1939
No. of Main Boilers Owners C. Maun, Belge (Lloyd's Register Owners' Address)
No. of Donkey Boilers Managers Agence Maritime Internationale Port Antwerp Voyage Longo
Steam Pressure in Main Boilers If Surveyed Afloat or in Dry Dock in Dry Dock Hoboken
in Donkey Boilers (State name of Dock.)

Last Report No. Port

Particulars of Examination and Repairs (if any) 1st entry Classification

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

How done: vessel placed in dry dock, propellers after ends of stern bush and fastenings of sea connections etc.

General Observations, Opinion, and Recommendation:— The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.S.M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

to far as ten. is in a good condition and eligible in my opinion to be classed as contemplated

Survey Fee (per Section 29) £ : : Fees applied for 19
Special Damage or Repair Fee (if any) £ : :
(per Section 29.)
Travelling expenses (if chargeable) £ : :
Received by me, 19

Committee's Minute

Assigned

See FE machy rpt.

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation
W1046-0010