

Subject to Stem, Stem plating and shell plate A2 and B2
port side being fairied at the Owners' convenience.

11

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

20 JUN 1939

VESSEL'S NAME

49723 (1/20)
SOUTHCOATES

Rpt.

Hul.

No.

49984

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey

The

Hull

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, ~~repairs to~~

and minor repairs effected.

The Stem and bow plating, as above, continue efficient

It is submitted the vessel appears worthy to remain as
classed with record of survey *5.39* ^{*Subject as above*} as recommended.

*100 A1
Stm Drafter .
5.39 Hul.*

Subject etc.

PLATING to be DRILLED when
vessel is 20 years old
or at next special survey
thereafter.



© 2020

Lloyd's Register
Foundation

L1075-0039