

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

Date of writing Report 20/3/50 When handed in at Local Office 20/3/50 Port of Aberdeen (Received at London Office 30 MAR 1950)

No. in Survey held at Aberdeen Date. First Survey 12/4/49 Last Survey 20/3/50 (No. of Visits 5)

05614 on the Machinery of the Wood, Iron or Steel Straw Trawler "City of Edinburgh"

Tonnage { Gross 88 Vessel built at Selby By whom Messrs Bochane & Sons When 1907 Month 5
 Net 32 Engines made at Luton By whom Messrs Vauxhall & West Hydraulic When .
 Nominal Horse Power 34 Boilers, when made (Main) 1907 (Donkey) Engineering Co. Ltd.
 No. of Main Boilers One Owners Department of Scientific and Industrial Research Managers' Address .
 No. of Donkey Boilers Two Managers G.F. Reay Port Aberdeen Voyage .
 Steam Pressure in Main Boilers 140 lbs If Surveyed Afloat or in Dry Dock Both (State name of Dock) Vic Dock + No 1 Porton
 in Donkey Boilers .

Last Report No. . Port .

Particulars of Examination and Repairs (if any) Docking, TS + BS.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined Yes

Was a damage report made by anyone else? If so, by whom? Yes

Did the Surveyor personally go inside ~~each~~ Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " " Yes

If not, state for what reasons Yes What parts of the Boilers could not be thus thoroughly examined? Yes

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Yes

State latest date of internal examination of each boiler 13/4/49 Present condition of funnel Efficient

Did the Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of the Donkey Boilers? Yes To what pressure were they afterwards adjusted under steam? Yes

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? Yes

Did the Surveyor examine all the mountings of the Main Boilers? Yes and of the Donkey Boilers? Yes

Has the screw shaft now been drawn and examined? Yes Has it a continuous liner? No Is an approved oil retaining appliance fitted at the after end? No

Has shaft now been changed? No If so, state reasons Yes Has the shaft now fitted been previously used? Yes Has it a continuous liner? Yes

Is an approved oil retaining appliance fitted at the after end? Yes State date of examination of Screw Shaft 14/4/49 State the wear down in the stern bush 1/16 Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? No

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done To complete the boiler survey,

four wanted rivet heads on engine c/c wrapper plate have to be dealt with, boiler examined under steam and safety-valves adjusted & set to W.P. Now done: - Vessel placed dry on porton. Propeller, screwshaft (down) and stembrake and outside fastenings examined. The T.S. specially examined and found efficient but it is recommended that 12 mths limit for period between examinations should still apply.

Boiler survey: - The boiler examined throughout with all mountings and fastenings. A general examination for condition of Machinery for postponement of LMC was arranged for but with the exception of the main steam pipe which has been annealed, tested and examined internally and found satisfactory, nothing further has been done to forward this. The former owner do not intend to continue with the examination and it is understood that vessel has been handed over to an Admiralty section for disposal.

General Observations, Opinion, and Recommendation: - The machinery of this vessel so far as

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 2,11, B&MS 2,11 or LMC 2,11 or LMC 140 lb., FD, &c.)

now seen is in efficient condition and eligible in my opinion to remain as now classed and to have record of BS. (with date) when the survey is completed subject to the screwshaft being re-examined by 4.50. and completion of examination of machinery

Survey Fee (per Section 29) BS 4:0:0 Fees applied for 24.3.1950
T.S.C.L. 1:0:0
 Special Damage or Repair Fee (if any) £ : :
 (per Section 29.)
 Travelling expenses (if chargeable) £ : :
 Received by me, P.H.W. Evans
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute GLASGOW 29 MAR 1950

Assigned Transmit to London



THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.
 If Stockists, state Mechanical Test.

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to W1083-0049

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]

RETA

13 | + | + | 21

RETA

22 + 27, pushed

Q.F. Roll 1/2 July 22
BE - 20/1/18/22

[Handwritten notes and scribbles, including the word 'RETA' written multiple times in green ink.]

OR 1/2/02