

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be reported as follows:

(Turn Screws
pre & aft)

London Rpt 93432 a

T.S. "M.O.P.5 B.A."

Built 10-1928 for the Argentine Government.

The vessel's class is subject to the forward propeller shafts and propellers, removed on account of damage, being refitted on arrival at the Argentina.

The Buenos Aires Surveyors have been advised and in reply state that the Argentine Government do not desire to retain the vessel's class in the Register Book.

IT IS SUBMITTED the vessel's class be withdrawn and three dots inserted, indicating withdrawal at the Owners' request.

Withdraw class.

Insert ...

14.1.29.



© 2020

Lloyd's Register Foundation

W1099-0095

Repair Fee (if any)	£	:	:	Fees applied for,
					10