

Port

San Francisco

m, 1.18.

Received from Chief Surveyors

to Chief Surveyors

VESSEL'S NAME STEEL S.S. "MONASSES" Report S. Fo. No. 3115

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

nature of Survey

When due

The Downton Pump has been dispensed with for the present.

✱ 100 A.1. (steel) "Shelter deck with Freeboard."

1 OK (steel) and Shelter dk (steel) and Webframes.

Longitudinal framing.

Cell DB 348' 1351t MT 30' 554t. FPT 73t. APT 48t.


FK. 4 BH to Shelter Deck. 3 BH to upper dk. pt. com.

Lloyd's A.&C.P. P34', F39' on Shelter OK.

Date of Build 6-19.

See 11/9/19

The Surveyors should be requested to state clearly how many bulkheads as required by Rules for bulkheads are stiffened and watertight to shelter deck, for record in Register, as the number given in report does not agree with the plans.



Lloyd's Register
Foundation

WH29-0030

Instructions

date

Noted for posting