

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 26 JAN 1942)

|                                   |   |                                   |                    |  |                       |              |
|-----------------------------------|---|-----------------------------------|--------------------|--|-----------------------|--------------|
| Date of writing Report            | 21-1-42                                     | When handed in at Local Office    | 23-1-42            | Port of  | Falmouth              |              |
| No. in<br>eg. Book                | Survey held at Falmouth                     |                                   | Date, First Survey | 20-8-41  | Last Survey           | 13-1-42      |
| 16881                             | on the Machinery of the Wood, Iron or Steel |                                   | M.S. "KONGSGAARD"  | (No. of Visits 13)   |                       |              |
| Gross<br>tonnage                  | 9467  | Net                               | 5677               | By whom  | Hockums M.V. Aukiteb  | Year. Month. |
| Nominal<br>Horse Power            | 1358  | Engines made at                   | Do                 | By whom  | Do                    | When 1937 8  |
| No. of Main Boilers               | -   | Boilers, when made (Main)         | Do                 | (Donkey)   | 1937                  | When 1937    |
| No. of Donkey Boilers             | 2   | Owners                            | Shibayashi Salvage | Owners' Address  | Port Slavanger Voyage |              |
| team Pressure—<br>in Main Boilers | "   | Managers                          | A. Gjorvold Olsen  | (if not already recorded in Appendix to Register Book.)  |                       |              |
| In Donkey Boilers                 | 1716  | If Surveyed Afloat or in Dry Dock | 17-3 Dry dock      | Particulars of Classification (which must be inserted<br>precisely as in Register Book & Supplements). |                       |              |
| (State name of Dock.)             |   |                                   |                    |  |                       |              |

Last Report No.

Port

Docking Damage

## Particulars of Examination and Repairs (if any) Part I.S. P.B.S.

Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? none

Donkey " "

+100A1 2-41

+L.M.C 8-37  
D.B.S 9-40  
P.S. 2-41 C.L.

Oil Engines

Continuous Survey.

This was not done, state for what reasons?

and what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler P.S 2/12/41

Present condition of funnel good

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? yes

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers? yes

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers? yes

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers? yes

Has screw shaft now been drawn and examined? no

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 932

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted yes

so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

as the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

See form 7E

Vessel placed in dry dock. The propeller, aft end of stern bush, sea cocks and valves with their fastenings examined.  
Main Engines N° 1-6 cylinders, covers, valves, pistons, rods, crossheads and bearings;  
N° 2 cylinder, cover, valves, piston and rod. all crank shaft pins and bearings;  
N° 1-2-3-6-7 crank shaft journals and bearings; seaway pump, crosshead and crank pin and forward crank journal and bearings examined and found in satisfactory condition. All auxiliary machinery examined 2/12/41  
Auxiliary Machinery Port and starboard auxiliary oil engine generators; all cylinders, covers, valves, valve gear, pistons, rods, top and bottom ends and crank shaft journals examined and found in satisfactory condition. 2/12/41

General Observations, Opinion, and Recommendation:—The machinery of this vessel, so far as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9-11, B&W.S. 9-11, +L.M.C. 9-11, or +L.M.C. 140 lb. F.D., &c.)  
CS 2, 3, 4, is in safe working condition and eligible in my opinion to remain as listed and to have record of +L.M.C. C.S. with date of completion of the survey and P.B.S 1-42. The vessel name to be deleted from Special Reasons list in respect of N° 1-6 main engines cylinder covers.

Survey Fee (per Section 29) £ 3 0 0  
Special Damage or Repair Fee (per Section 29) £ 6 6 0  
Travelling expenses (if chargeable) £ : :  
Licence Fee F.R. 18 FEB 1942

Fees applied for  
13th Jan 1942  
Received by me,  
19

Admiral  
Engineer Surveyor to Lloyd's Register of Shipping.  
R 2020

Committee's Minute

Assigned

D.B.S. 1-42  
Without Opt. Cons  
Date (WT. S.B.) 171 03

M.S. "KONGSGAARD"C.S. Continued

Two cylinder jacket cooling pumps (S.S); one cooling pump for auxiliary oil engine generator (S.S); one sanitary pump (S.S) examined and put in satisfactory condition. Main and auxiliary machinery

Two oil cooler channel and boiler and pumping arrangements examined under working conditions

Electric Equipment Electrical installation examined throughout and circuits megger tested. Generators and motors examined under working conditions and found satisfactory

Boiler Room Survey

Boiler tubes (2) examined internally and externally together with mountings, doors and fastenings and found in satisfactory condition

Boiler tube safety valves adjusted under steam to 171 lbs per sq. inch

Oil fuel installation examined under working conditions; the fuel tank valves, deck control gear, oil discharge pipes between pumpes and furnaces found satisfactory

Weast Team Repairs

Main engine. N° 1-6 cylinders cores removed, as recommended.

N° 2 Top half of bottom and bearing shell fractured, new bottom and bearing complete fitted

Auxiliary oil engine generators

Pst engine, N° 3 bottom and remetalled. crank shaft pins lapped and bearings adjusted. Piston grooves machined and new rings fitted

Starboard engine. N° 1 bottom and remetalled, crank shaft pins lapped and bearings adjusted. Piston grooves machined and new rings fitted

Sanitary Pump. Impeller shaft removed, impeller machined and new bearings fitted

N° 2 main engine cylinder jacket cooling pump, impeller shaft removed (S.S)

Sea connections - boiler mounting overhauled and fastened

Electric installation generally overhauled; wiring channel and terminals

Damage stated to have been caused through the recent being in collision with the steamer "TREWORLAS" on the 17<sup>th</sup> June 1941

Condenser overboard discharging pipe removed. Pst Pipe

All valves on ship's side in way of damaged shell flange removed, opened up, examined and refitted.

S.R.L N° 1-6 main engine cylinder cores dealt with at this time

it stated

NOTE The "La Mout" boiler has been removed and is not likely to be refitted.



© 2020

Lloyd's Register  
Foundation

10/1/42 Chardaneed  
S&L held.  
da Mont Boiles taken ashore  
10/15/42 coxes renewed

DT 1.42  
without special condition

DTA  
11/3/42

In A. Delete  
DTB(WT)  
17/6/42

© 2020



Lloyd's Register  
Foundation