

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19-3-17 When handed in at Local Office 30/3-17

Port of Hull

No. in Reg. Book 1007

Survey held at Hull

Date, First Survey 15-3-17

Last Survey 21-3-1917

(No. of Visits 2)

Master B. F. Brett

TONNAGE:-

GROSS 196

UNDER DE. 175

NET 24

Built at North Shields

By whom Smith's D. Co. Ltd.

Owners Harley & Miller Ltd.

When 1904

MONTH 11

Port belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Albert St.

Destined Voyage Fishing

WB=Cell DBor DBa

feet; uE&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet - tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 76119 Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. For Special Survey. Date of last Survey and of Periodical Survey.	Machine and Boiler Surveys (including date of N.E., if any).
100 A.1.	BS. 3.16
5TH TRAWLER	BS. 3.16
7.16	BS. 3.16
5.11.11 N° 2-13	BS. 3.16

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? No damage

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Boiler:-

Completion of 55. A° 3 and fitting new

Now done:- Boiler casing removed, and boiler lifted out. Frames reverse frames and bunker walls cleaned and examined. Casing found satisfactory. Bunker wall plates on port side 2 off, cropped and lower part renewed. 2 reverse frames on starboard side renewed. Casing over boilers, lower part of same renewed and connections to beams made good. Wood deck in way of boiler casing renewed, caulked, and payed.

SUMMARY OF DAMAGE REPAIRS:-

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks Good
Caulking of Decks
Waterways
Coamings
Beams & Fastenings where seen
Outside Plating
Caulking of ditto
Rivets
Breasthooks & Crutches
Transoms where seen
Frames where seen
Reverse Frames
Floors
Keelsons

Stringers Good
Inner Bottom Plating
State if Tanks have been examined inside
State if Tanks now tested
Bulkheads Good
Ceiling
Cement or Asphalt (State which) where seen
Rudder
Steering gear and its connections
Windlass
Have Pumps now been examined and found efficient? No
Have Sluice Valves now been examined and found efficient?
Have Watertight Doors now been examined and found efficient? No

Dblg. Plates under Sounding Pipes
Engine Room Skylights
Coal Bunkers, Open'gs, Lids, &c.
Scuppers
Cargo Hatchways
Hatches
Planking of Wood Vessels
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shells ditto
Selling (State if examined.) ditto

Copper, or I.M. of Wood Vessels (State if on felt.)
When put on, Month
Boats Good
Masts, Yards, &c.
Condition, how ascertained from deck (State if wedges removed) No
Sails
Equipment letter
Anchors, No. of 3
Cables (State if now ranged) No
" length size
(on board)
" Rule length size
Hawser & Warps. Insufficient
Standing & Running Rigging Good.

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,1,1," or "to remain as classed and to have record of survey, 1,1,1, and the notations of ss No. 1-11 and ptND11, &c."

This vessel is now, so far as seen, in a good and efficient condition and is eligible in my opinion to remain as classed without fresh record of survey and the notation of 55. L.V. N° 3

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

Received by me,

Matthew Blackwood

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character Assigned

THU. 5 APR. 1917

100 A.1. Sm. Trawler

ss. No. 3-2, 17

+ A.B. 3.17

HULL CERTIFICATE
WRITTEN 10-4-17

© 2020

Lloyd's Register
Foundation

W133-0034