

"WILLIAM BELL"

In November 1938 this vessel's class was withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at the Owners' request.

The Owners request a Classification Survey be held on this vessel. (See L.S. Letter 14/12/45)

The GLASGOW Surveyors report (2.46) this vessel placed in dry dock and a Survey carried out, after which the Owners decided, on account of the large amount of work to be done to complete and equip the vessel for fishing services, that work should be discontinued and the vessel scrapped.

It is accordingly submitted no action is necessary in this case.

8.3.46.



© 2021
Lloyd's Register
Foundation

W1345-0220

Have the Tanks been examined internally?.....

Air and Sounding Pipes.....

Stringers, Clamps & Shelves.....

Salting.....