

## Amesbury Esquimalt

This vessel put into Port Said with damage to Starboard oil engine. In 3-19 the Port Said surveyor reported that this engine was damaged and repairs or renewal at her port. and that a good hand donkey boiler, in good condition, had been on board to replace the old donkey boiler which was removed to the hold. The age & makers of boiler are not known & sufficient particulars are not given of the boiler in order to fix a safe working pressure, but the surveyor adjusted the safety valves to 15 lbs.

In February the Marcella Surveyor stated that a vessel has new engines & donkey boiler fitted, & forwarded a letter from the new Owners stating that they wished to retain the screw class & would forward the name of the motor to the Marcella Surveyor. On August 13<sup>th</sup> the Marcella Surveyor stated that a vessel was still laid up & that they had received no further communications.

To complete the Survey for the retention of the screw class, particulars of the new motor or motors will require to be forwarded to this office for approval. Particulars of the donkey boiler, sufficient to enable a safe working pressure to be calculated, also forwarded.

J.W.D.

22/9/21



© 2021

Lloyd's Register  
Foundation

W1382-0055

1600-2851M