

Runden

How Emden

Dr. 8.12.

1

Received from Chief Surveyors

Sent to Chief Surveyors *19/2/13.*

VESSEL'S NAME *St H Lancashire*

Report *Go*

No *32350*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32)

Nature of Survey *First entry*


When due

*+ 100 A-1. (2nd) Shelter deck with foreboard
2 Dr (2th) + Shelter Dr (2th)
NB: Cul DBa 11' n 3' 4' 366' 15H 977L Dta 30' 793 L FPT 58L
FK, Iron Dr BH in after hold dispensed with SBH to
Shelter Dr 1 BH to 2nd Dr only. Lloyd's at 6P.*

*M. R/BH
19/2/13*

E. G. C.

RETAIN



© 2021

Lloyd's Register
Foundation

W1441-0076