

Nº A. 140.

All plates, rivets & stay bars to be of Siemens Martin steel.
The first 3000s throughout the boiler to be drilled in place
after the plates are bent.
The flange plates to be annealed after bending.
The screw stays are $1\frac{1}{8}$, $1\frac{1}{2}$ & $1\frac{3}{4}$ in diam screwed into both
plates and nutted at steam. We screwed 10 heads feet inch.

Nº A. 140.


To Lloyd's

Messrs Earles & Co

Boiler No A 140

Hull Report No. 23391


No 1471
Lloyds Test
260 lbs.
J.B
19.9.10



S.S. Atelvina

Olto & Zanen 525.

RETURN



© 2021

Lloyd's Register
Foundation

W11444-0141

Harvey

W1444-0141



© 2021

Lloyd's Register
Foundation