

WRECK SECTION

Rpt. 8.

No. 55775

(Received at London Office)

No. 55775

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 20 JUN 1949... Port of... HULL.

No. in Survey held at... HULL. Date, First Survey and Last Survey... 22. 6. 19 49.

Reg. Book. 57325 on the Wood, Iron or Steel "EARL KITCHENER". TONNAGE: 5770 GROSS 348 UNDER DK 311 NET 162

Built at Beverley By whom Cook, Welton & Gemmell, Ltd. When 1915 7

Owners Lord Line, Ltd. Owners' Address... Port belonging to Hull

Surveyed Afloat or on slipway Both Name of Dock St. Andrew's Dock. Destined Voyage Fishing

Cell D Bor D Ba... feet; uE & B... feet; f... feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Table with 2 columns: CHARACTER (e.g., +100A1 Steam, Trawler 6,48, s.s.Hul. 2nd, No.3-3,39, s.s.Shl. -8,47) and Machinery and Boiler Surveys (e.g., +IMC 8,47, BS 6,48, TSCL 11,47)

N.B. - All alterations in the existing records should be underlined. Last Report, No. 54961. Port Hull.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking & Condition.

NOW DONE:- Vessel placed on slipway. Shell plating, sternframe and rudder cleaned, examined and recoated. Last seen on slipway 22.6.49.

Holds, machinery spaces, decks, casings, coamings, hatchways, ventilators, closing appliances, steering gear, windlass, general equipment generally examined and found satisfactory.

S.R.L. Item:- Plate B.2 s.s.a. examined and considered in no way to affect seaworthiness of vessel and as such may be made an endorsement item.

Repairs:- 15 fathoms 1 1/2" stud link anchor cable placed on board & verified from certificate to replace 15 fathoms placed on "Snow" anchor. Details overleaf.

SUMMARY OF DAMAGE REPAIRS table with columns: Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Beams, Inner Bottom Plates, Dk. Plates, Other Items

PRESENT CONDITION OF THE table with columns: Decks, Bulkheads, Engine Room Skylights, Copper, or Y.M., Caulking of Decks, Ceiling, Coal Bunkers, Openings, Covers, &c., When fitted, Month, Year, Coamings, Cement or Asphalt, Oil Bunkers, Boats, Beams & Fastenings, Rudder, Scuppers, Masts, Yards &c., Outside Plating, Steering gear and its connections, Cargo Hatchways, Condition, how ascertained, Frames, Reverse Frames, Have pumps been examined and found efficient?, Planking, Equipment letter, Longitudinals, Have Sluice Valves been examined and found efficient?, Caulking, Anchors, No., Transverses, Have Watertight Doors been examined and found efficient?, Treenails, Cables, Floors, Have Ventilators and their Coamings been examined and found efficient?, Breasthooks & Stemson, length, mean diamr., Keelsons, Air and Sounding Pipes, Transoms, Pointers & Crutches, Rule length, size, Stringers, Doubling Plates under Sounding Pipes, Timbers of Frame at openings, Chain Locker, Inner Bottom Plating, Salting, Stringers, Clamps & Shelves, Hawser & Wires, Standing and Bottom Rigging, Have the Tanks been tested?, Sails

General Observations, Opinion as to Class, Recommendation, &c.:- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is eligible in my opinion to remain as classed with fresh record of Docking 6,49.

Fees table with columns: Survey Fee, Special Damage or Repair Fee, Travelling Expenses, Second Surveyor's Fee, Fees applied for, Received by me

Committee's Minute WED 3 AUG 1949 Character Assigned 6.49. Hul. without spl cond... 138.6.49

