

COPY

LLOYD'S REGISTER OF SHIPPING.



Hong Kong

May 21st. 1927.

S. S. "TJILDEORT"

EXAMINATION OF DAMAGE REPORT DATED MAY 5TH. 1927.

An examination, as much as possible, was made, on May 5th. 1927, of the fore end of the above vessel, as it now lies on the Island, and the Undersigned found the fore end hard and the Rocks, with bottom very badly damaged and beyond salvage.

It is recommended however, that, given good weather, the parts of the vessel might be removed and delivered to the Repairers, to be used in the construction of a new fore end, subject parts being examined and found satisfactory and suitable on arrival at the Repairers premises:-

part of stem from about the 25 feet mark.

ass, hawsse pipes, chain pipes, deck stoppers, anchor cables & one bower anchor.

bulwark rising plates on forecastle head.

forecastle deck plating & beams (except stringer plates).

forecastle deck plating & beams (except stringer plates).


deck plating & beams (except stringer plates) together with hatch coamings, hatch beams, part wood hatches, & two coal bins with hinged doors.

deck plating & beams (except stringer plates) together with hatch coamings, hatch beams & part wood hatches.

deck beams, hatch coamings, & hatch beams in No.1 hold.
This is a wood deck only.

deck plating & beams (except stringer plates) together with hatch coaming, hatch beams, part wood hatches, two deck bins and one companion entrance.

peak bulkhead plates (except wing plates) from upper deck P. tank top.



© 2019

Lloyd's Register
Foundation
W223-0156(12)

- (11) Bridge front bulkhead plating (except wing plates) including stiffeners & two W.T. doors.
- (12) Tween deck bulkhead plating (except wing plates) between No.1 and 2 holds.
- (13) Silk room plating & stiffeners (except top coaming) together with door.
- (14) Wash port & cargo port doors and all scuttle ports.
- (15) Twin masts, rigging, two mampson posts, derricks & winches.
- (16) Hold ladders and companion ladders.
- (17) All ventilators, ventilator coamings, bellards, fairleads, stanchions where practicable, and wire reels.
- (18) Handrails, rail stanchions, awning stanchions.
- (19) Goose neck air pipes & brass caps to sounding pipes.
- (20) Three skylights complete on forecastle head.
- (21) One fresh water tank on forecastle head.
- (22) All deck steam pipes & steam pipe covers.
- (23) One stove and copper tank in forecastle galley.
- (24) All forged small deck fittings.
- (25) All hand pumps, electric fittings & steam heaters with piping to same.
- (26) Teak doors and name plates, wood gratings, iron bunks, and deck lights.
- (27) Fore peak air valves.

NOTE:- Sufficient deck beams will require to be left in place to prevent sides of vessel collapsing on workmen, say about every 5th beam and it is probable that these beams will not be salvaged from the wreck.

It is not proposed to remove the side plating or part of the frames, for structural reasons, as it is doubtful whether these parts could be satisfactorily worked into the construction of a new fore end, due to the possibility of unfair holes etc.

J.S. Morrison
SURVEYOR TO LLOYD'S REGISTER
HONGKONG



© 2019

Lloyd's Register
WF22310156 (2/2)