

1m.3.43.

V.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "FORT BUCKINGHAM" REPORT Bom. No. 7451

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to (a bower anchor and 45 fathoms of chain cable being supplied and 2 bower anchors and stream anchor on board being submitted to the Statutory Test).

The BOMBAY Surveyors report (11.43) the vessel afloat and the loss of a bower anchor and about 40 fathoms of chain cable.

A bower anchor weighing 63½ cwts. from the m.v. "BRITISH PURPOSE" a classed vessel, has been placed on board together with 45 fathoms of 2¼" chain cable.

IT IS SUBMITTED the vessel be continued as classed with record of docking survey 11.43 subject to (a bower anchor and 45 fathoms of chain cable being supplied) and to one bower anchor and stream anchor on board being submitted to the Statutory Test), and to a bower anchor & 45 fathoms of chain cable of correct size, weight and test being supplied to replace temporary equipment at the 11.43 Bom. subject. first convenient opportunity.

Amend S.R.L.

8.3.44

BAH

Reported sunk by submarine.



© 2019

Lloyd's Register Foundation

W 244-0062

Bottom Plating.....

examined and found efficient ?.....

Salting

(State if examined.)

ditto.....

Standing and Running R